PRIORITY 2

(NUDOCS OFFSITE FACILITY)
REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9408240005 DOC.DATE: 94/08/12 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
AUTH.NAME AUTHOR AFFILIATION
AXELSON,W.L. Region 3 (Post 820201)
RECIP.NAME RECIPIENT AFFILIATION
FITZPATRICK,E. Indiana Michigan Power Co.

P

U

Μ

F

SUBJECT: Forwards insp repts 50-315/94-16 & 50-316/94-16 on 940718-22. Noncited violations identified.

DISTRIBUTION CODE: IE06D COPIES RECEIVED:LTR LENCL SIZE: 3+13
TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

NOTES:

	RECIPIENT ID CODE/NAME PD3-1 PD			COPIES LTTR ENCL l l		RECIPIENT ID CODE/NAME HICKMAN,J		COPIES LTTR ENCL l l		R
							LTTR 1			i
INTERNAL:	AEOD/SPD			1	1	AEOD/TTC	1	1		Т
	NMSS/SG	TB	4E4	l	1	NRR/DREP/PRPB10	2	2		
	NRR/PMAS/ILRB12 NUDOCS-ABSTRACT OGC/HDS2			1	1	NRR/PMAS/IRCB-E	1	1		V
				1	1	OE_DIR_	1	1		1
				1	1	REG FILE 02	1	1		
	RES	+		1	1	RGN3 DRSS/RPB	1	1		
	RGN3	FILE	01	1	1	RGN4/FIPS	ī	ı		2
TERNAL:	NOAC			1	1	NRC PDR	1	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

, 1¹ ţ

Docket No. 50-315 Docket No. 50-316

Indiana Michigan Power Company ATTN: Mr. E. E. Fitzpatrick Senior Vice President Nuclear Generation 1 Riverside Plaza Columbus, OH 43216

Dear Mr. Fitzpatrick:

SUBJECT: ROUTINE CHEMISTRY INSPECTION AT THE D. C. COOK NUCLEAR PLANT

ON JULY 18 THROUGH 22, 1994

This refers to the routine safety inspection conducted by Dr. John House and Mr. Steven Orth of this office on July 18-22, 1994. The inspection included a review of authorized activities at your D. C. Cook Nuclear Plant facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, interviews with personnel, and observation of activities in progress. In addition, our Mobile Laboratory was at the site during the inspection to perform independent measurements of radioactivity.

Based on the results of this inspection and your identification of repetitive problems in the chemistry area, we were concerned with the quality and depth of your staff's evaluations and corrective actions associated with chemistry program weaknesses. The strengths in identifying problems have been overshadowed by weaknesses in problem evaluation and resolution. Root cause evaluations appeared to be narrowly focused, and corrective actions were not comprehensive which resulted in repetitive problems in your chemistry program. We encourage your aggressive self identification of problems and acknowledge the recent steps you have taken to strengthen chemistry management, however, your evaluation and resolution of problems must continue to improve in order to effect positive programmatic changes. Two non-cited violations were identified.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

9408240005 940812 PDR ADDCK 05000315 G PDR

I CP

Indiana Michigan Power Company

2 AUG 1 2 1994

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Division of Radiation Saféty

and Safeguards

Enclosure: Inspection Reports No. 50-315/94016(DRSS); No. 50-316/94016(DRSS)

cc w/enclosure: A. A. Blind, Plant Manager OC/LFDCB Resident Inspector, RIII James R. Padgett, Michigan Public Service Commission Michigan Department of Public Health D. C. Cook, LPM, NRR IPAS (E-Mail).

bcc: w/enclosure PUBLIC IE06

(SEE ATTACHED SHEET)

RIII RIII

RIII

RIII

RIII 1

House/jp 08/ /94

Orth

McCormick-Barger

Kropp

Pederson

2

We will gladly discuss any questions you have concerning this inspection. Sincerely,

Cynthia D. Pederson, Chief Reactor Support Programs Branch

Enclosure: Inspection Reports No. 50-315/94016(DRSS); No. 50-316/94016(DRSS)

cc w/enclosure:
A. A. Blind, Plant Manager
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan Public
Service Commission
Michigan Department of
Public Health
D. C. Cook, LPM, NRR
IPAS (E-Mail)

bcc: w/enclosure
PUBLIC IE06

RIII Withouse/jp 08/にア/94 RIII Smbl Ortho 3/9

RIII 97765 McCormick-Barger RIII Kropp

RIFI
Pedersor

RIII Omensorio Axelsorio