

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9502210149 DOC. DATE: 95/02/10 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH. NAME AUTHOR AFFILIATION
 KROPP, W.J. Region 3 (Post 820201)
 RECIP. NAME RECIPIENT AFFILIATION
 FITZPATRICK, E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 SUBJECT: Forwards insp repts 50-315/94-24 & 50-316/94-24 on 941217-
 950130. No violations noted.
 DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+17
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 PD	1 1	HICKMAN, J	1 1
INTERNAL:	AEOD/DEIB	1 1	AEOD/SPD/RAB	1 1
	AEOD/SPD/RRAB	1 1	AEOD/TTC	1 1
	DEDRO	1 1	FILE CENTER 02	1 1
	NRR/DISP/PIPB	1 1	NRR/DORS/OEAB	1 1
	NRR/DRCH/HHFB	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	OGC/HDS2	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 18

DCC
SRI.

February 10, 1995

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Senior Vice President
Nuclear Generation
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by Messrs. J. Isom, D. Hartland, C. Orsini, and R. Bywater of this office from December 17, 1994 through January 30, 1995. The inspection included a review of activities at your Donald C. Cook Nuclear Plant, Units 1 and 2. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during this inspection. However, we did identify one area of concern. Previous inspection reports 50-315/94018 and 50-316/94018 documented problems regarding failure to remove action request (AR) tags upon resolution of the deficiencies documented on the tags. While your long term corrective actions are not due for completion until June 1, 1995, this inspection showed that isolated examples are still occurring. We understand that you plan to reassess your interim corrective actions. This area will be monitored during future inspections.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by
I. N. Jackiw for
Wayne J. Kropp, Chief
Reactor Projects Section 2A

Docket No. 50-315
Docket No. 50-316

(See attached distribution)

9502210149 950210
PDR ADDCK 05000315
Q PDR

TEO/11

Enclosure:

Inspection Report No.
50-315/94024(DRP);
50-316/94024(DRP)

Distribution:

cc w/encl: A. A. Blind, Plant Manager
James R. Padgett, Michigan Public
Service Commission
Michigan Department of
Public Health

Distribution:

Docket File w/encl
PUBLIC IE-01 w/encl
OC/LFDCB w/encl
SRI, D. C. Cook w/encl

DRP w/encl
RIII PRR w/encl
D. C. Cook, PM, NRR w/encl
IPAS (E-Mail) w/encl

Document: R:\insprpts\powers\cook\dcc94024.drp

To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII		RIII		RIII		RIII	
NAME	Jackiw		Jacobson		Shaffer		Pirok		Kropp	
DATE	02/10/95		2/10/95		02/10/95		02/10/95		02/10/95	

OFFICIAL RECORD COPY

