CATEGORY 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CESSION NBR: 9806150236 . DOC.DATE: 98/06/09 NOTARIZED: NO DOCKET # ACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316 AUTHOR AFFILIATION AUTH.NAME GROBE, J.A. RECIPIENT AFFILIATION RECIP.NAME American Electric Power Co., Inc. SAMPSON, J. C

SUBJECT: Forwards special RP insp repts 50-315/98-13 & 50-316/98-13 on 980601-02. One violation of NRC requirements identified re failure to notify RP of open wound prior to entry into radiologically controlled area:

DISTRIBUTION CODE: IE06F COPIES RECEIVED:LTR / ENCL / SIZE: Ε TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

NOTES:

	RECIPIENT ID CODE/NAME PD3-3 PD	COPIES LTTR ENCL 1 1	. RECIPIENT ID CODE/NAME STANG,J	COPIES LTTR ENCL 1 1	R
INTERNAL:	AEOD/TTC NMSS/SFPO 06F18 NUDOCS-ABSTRACT OGC/HDS3	$ \begin{array}{cccc} 1 & 1 \\ 1 & 1 \\ 1 & 1 \\ 1 & 1 \end{array} $	FILE CENTER NRR/DRPM/PERB OE DIR RGN3 FILE 01	1 1 1 1 1 1 1 1	¥ 2 ·
UTERNAL:	NOAC NUDOCS FULLTEXT	1 1 1 1	NRC PDR	1 1	D

OADED FROM **NRC FLOPPY**

A

Т

G

0

C

ΰ

М

E


N

T

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL

DESK (DCD) ON EXTENSION 415-2083

13 TOTAL NUMBER OF COPIES REQUIRED: LTTR 13 ENCL



, . ,

*

.

4 • • •

·

.



June 9, 1998



Mr. John Sampson Site Vice President Nuclear Generation Group American Electric Power Company 500 Circle Drive Buchanan, MI 49107-1395

SUBJECT: NRC SPECIAL RADIATION PROTECTION INSPECTION REPORTS 50-315/98013(DRS); 50-316/98013(DRS) AND NOTICE OF VIOLATION

Dear Mr. Sampson:

980615023

PDR

ADDCK

0500

On June 2, 1998, the NRC completed a special inspection at your D. C. Cook, Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The purpose of the inspection was to follow up on an event where a worker entered containment with an open wound without prior notification of the presence of the wound to radiation protection personnel. The enclosed report documents the results of the inspection.

One violation of NRC requirements was identified, as specified in the enclosed Notice of Violation (Notice). The violation concerned the failure to notify radiation protection of an open wound prior to entry into a radiologically controlled area. This violation is of concern because there were several opportunities to notify radiation protection of the wound. Neither the worker, his foreman, or the safety supervisor notified radiation protection of the presence of the wound.

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence, is already adequately addressed in the subject inspection report. Therefore, you are not required to respond to this violation unless the description of the problem as described in the inspection report does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

In accordance with 10 CFR 2.790 of the NRC'S "Rules of Practice," a copy of this letter, the enclosures, and your response to this letter, if you choose to provide one, will be placed in the NRC Public Document Room (PDR).




.

· .

· · · ·

. • • • • .



.





J. Sampson

2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by John A. Grobe

John A. Grobe, Director Division of Reactor Safety

Docket Nos. 50-315; 50-316 License Nos. DPR-58; DPR-74

Enclosures: 1. Notice of Violation 2. Inspection Reports 50-315/98013(DRS); 50-316/98013(DRS)

cc w/encls:

 Don Hafer, Acting Chief Nuclear Engineer
 Douglas Cooper, Plant Manager Richard Whale, Michigan Public Service Commission
 Michigan Department of Environmental Quality
 Emergency Management
 Division, MI Department
 of State Police
 David A. Lochbaum, Union
 of Concerned Scientists

DOCUMENT NAME: G:DRS\DCC98013.DRS

OFFICE	RIII	ERIII	ERIILAY	K RIII
NAME	DNissen :jp 666	GShear 🥝	(S BBurgess	JGrobe
DATE	06/5/98	06/5/98	06/5/98	06/9/98

OFFICIAL RECORD COPY



•

.

•

• •

. • · · •

•

•

•

.

,

i

• •

.

,

ı

.

J. Sampson

Distribution: Project Mgr., NRR w/encls C. Paperiello, RIII w/encls J. Caldwell, RIII w/encls B. Clayton, RIII w/encls SRI DC Cook w/encls DRP w/encls TSS w/encls DRS w/encls RIII PRR w/encls PUBLIC IE-01 w/encls Docket File w/encls GREENS IEO (E-Mail) DOCDESK (E-Mail)

150020

3

٢

٠

. . -, • •

. .

·

. •

·.

.

·

•

ĸ

٠