



Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



December 16, 1998

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/98-050-00, "Ancillary Equipment Installed in Ice Condenser Not Designed to Withstand Design Basis Accident/Earthquake Loads."

The following commitments were identified in this submittal:

- A design change has been developed to upgrade the supports/restraints for certain large or concentrated areas of electrical equipment located inside the ice condenser. Installation of the design change will be completed prior to plant restart.
- Design criteria have been developed for the ice condenser ancillary equipment. These criteria will be incorporated into the Updated Final Safety Analysis Report.

Sincerely,

J. R. Sampson
Site Vice President

/mbd

Attachment

9812230144 981216
PDR ADOCK 05000315
S PDR

1/1
IE 22

c: J. L. Caldwell (Acting), Region III
R. P. Powers
P. A. Barrett
J. B. Kingseed
R. Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector

