

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

011 | F | L | T | P | S | 4 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 1 | 5

CONT

011

REPORT
SOURCE

L 5

0151010012511701311017193014101917193

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

013 | During cold shutdown while in preparation for the Unit 3 Engineered
013 | Safeguards Test, 2 cracks were observed in the 4B charging pump suction
014 | piping (4" type 304 stainless steel, schedule 10) adjacent to the weld
015 | between the suction piping and a drain line. The pump was removed from
016 | service. Two other charging pumps were operable, which satisfied the
017 | requirements of TS 3.6.b.1. Similar occurrences were reported in
018 | LER 250-78-3 and 251-78-4.

019

SYSTEM
CODE

P C 11

CAUSE
CODE

B 12

CAUSE
SUBCODE

B 13

COMPONENT CODE

P 1 P E X X 14

COMP.
SUBCODE

B 15

VALVE
SUBCODE

Z 16

(17) LER/RO
REPORT
NUMBEREVENT YEAR
7 9SEQUENTIAL
REPORT NO.
0 0 2OCCURRENCE
CODE
0 3REPORT
TYPE
LREVISION
NO.
0ACTION
TAKEN
B 13FUTURE
ACTION
F 19EFFECT
ON PLANT
Z 20SHUTDOWN
METHOD
Z 21HOURS
0 1 0 1 0 0ATTACHMENT
SUBMITTED
N 23NRC-4
FORM 508
N 24PRIME COMP.
SUPPORT
A 25COMPONENT
MANUFACTURER
S 1 0 2 9 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 | The design/installation of these positive displacement pumps results in
111 | operational pressure pulsation/vibration effects which most probably
112 | caused the cracks. Corrective action was to make a weld repair.
113 | Modifications to reduce cyclic stresses have been completed on Unit 3
114 | and will be completed on Unit 4 during the Spring 1979 refueling.

115

FACILITY
STATUS

G 25

% POWER

0101023

OTHER STATUS

NA

METHOD OF
DISCOVERY

A 31

DISCOVERY DESCRIPTION

Operator Observation 32

116

ACTIVITY
RELEASED

Z 33

CONTENT

Z 34

AMOUNT OF ACTIVITY

NA

LOCATION OF RELEASE

NA 36

117

PERSONNEL EXPOSURES
NUMBER

0 0 0 37

TYPE

Z 38

DESCRIPTION

NA 39

118

PERSONNEL INJURIES
NUMBER

0 0 1 40

DESCRIPTION

NA 41

119

LOSS OF OR DAMAGE TO FACILITY
TYPE

Z 42

DESCRIPTION

NA 43

120

PUBLICITY
ISSUED

N 44

DESCRIPTION

NA 45

NRC USE ONLY

NAME OF PREPARER

D. K. James

PHONE: (305) 552-3830

8904230292

