



FLORIDA POWER & LIGHT COMPANY

April 20, 1979

PRN-LI-79-129

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-79-6  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: MARCH 22, 1979

RCS LEAK RATE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30-day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt  
Vice President  
Power Resources

MAS/ms

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)  
Robert Lowenstein, Esquire  
File 933.1 TP

7905080567

4002  
5/1  
S

60607028