AUG '2 RESIDE ATORY DOCKET FILE COPY:

DISTRIBUTION: =Gentral Files NRC PDR **PSB** Reading NRR Reading

(7

MEMORANDUM FOR: A. Schwencer, Chief, Operating Reactors Branch #1, Division of Operating Reactors

FROM:

G. Lainas, Chief, Plant Systems Branch, Division of

Operating Reactors

SUBJECT:

TURKEY POINT PLANT, UNITS 3 AND 4 - SAFETY EVALUATION OF

SUSCEPTIBILITY OF SAFETY-RELATED EQUIPMENT/SYSTEM TO

FLOODING FROM FAILURE OF NON-CATEGORY I (SEISMIC) SYSTEMS

In response to technical assistance requests, TAC's 7962/3, enclosed is the Plant Systems Branch Safety Evaluation Report pertaining to the Turkey Point Plant Units 3 and 4, Susceptibility of Safety-Related Equipment/System to Flooding from Failure of Non-Category I (Seismac) Systems. We find the proposed protective measures acceptable.

> G. Lainas, Chief Plant Systems Branch Division of Operating Reactors

Enclosure: Safety Evaluation Report

cc w/enclosure:

D. Eisenhut

W. Russell

B. Grimes

W. Gammill

M. Grotenhuis

D. Verrelli

G. Lainas

D. Tondi

J. Burdoin

CONTACT: J. Burdoin

Ext. 28077

				١			meni p
office >	DØR:P8B	DOR: SLYPSB	þ	ወያ: PSB			
BURNAME≯	James oin:esp	DTorfth	G	1 /			
DATE	8//6/79	8/11/179	8	11,0/79		- 200 FEEL EAST-000 On COLUMN DOCUMENT APPROPRIATE CALLEGO.	
7009210251							

NRC FORM 318 (9-76) NRCM 0240

🛣 U. S. GOVERNMENT PRINTING OFFICE: 1976 - 626-624

<u>390</u>9%T00//

AND SPECIAL PROPERTY OF THE PR

The first tends of the control of th

The second s Second se

Form In the Second Seco

ስ 3 6 1 ዩኒቨርክ - • ፡ «ሽታ ነ ፡ ፡ ፡ ፡ ፡ ጀኒስር 1 ፡ ፡ ፡ ዓርስር 1971 - •

The office of the second

orzenes

1 1

HURBERT TO HE STONE TO A TO

KIND PROFES OF A PROPERTY.



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

AUG 20 1979

MEMORANDUM FOR: A. Schwencer, Chief, Operating Reactors Branch #1,

Division of Operating Reactors

FROM:

G. Lainas, Chief, Plant Systems Branch, Division of

Operating Reactors

SUBJECT:

TURKEY POINT PLANT, UNITS 3 AND 4 - SAFETY EVALUATION OF SUSCEPTIBILITY OF SAFETY-RELATED EQUIPMENT/SYSTEM TO

FLOODING FROM FAILURE OF NON-CATEGORY I (SEISMIC) SYSTEMS

In response to technical assistance requests, TAC's 79.62/3, enclosed is the Plant Systems Branch Safety Evaluation Report pertaining to the Turkey Point Plant Units 3 and 4, Susceptibility of Safety-Related Equipment/System to Flooding from Failure of Non-Category I (Seismic) Systems. We find the proposed protective measures acceptable.

> G. Lainas, Chief Plant Systems Branch Division of Operating Reactors

Enclosure: Safety Evaluation Report

cc w/enclosure:

D. Eisenhut

.W. Russell

B. Grimes

W. Gammill

M. Grotenhuis

D. Verrelli G. Lainas

D. Tondi

J. Burdoin

CONTACT: J. Burdoin

Ext. 28077