


Copy FILE
P.O. BOX 529100, MIAMI, FL 33152

USNRC REGION II
ATLANTA, GEORGIA



80 JUL 14 AIO: 12

July 9, 1980
L-80-218

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-250, 50-251
IE Bulletin 80-11

The information requested in Bulletin 80-11 is being prepared by our Architect-Engineer and is not complete at this time. Although the report is not completely finished, the safety related walls have been identified and a re-evaluation program has been developed. The finished report will be submitted by July 23, 1980.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/pa

cc: Director, Division of Reactor Construction Inspection
Harold F. Reis, Esquire

8007250262

