

OCTOBER 21 1980

Docket Nos. 50-250  
and 50-251

Dr. Robert E. Uhrig, Vice President  
Advanced Systems and Technology  
Florida Power and Light Company  
Post Office Box 529100  
Miami, Florida 33152

Dear Dr. Uhrig:

Our review of the Turkey Point Plant Steam Generator Repair Report for the Turkey Point Plant Unit Nos. 3 and 4 includes the evaluation of various alternatives for disposal of the steam generator lower assemblies. Two proposed alternatives are the onsite storage and the intact shipment offsite to a licensed burial facility. We find that we need the information described in the enclosure to this letter in order to evaluate these alternatives properly. Please respond to the enclosed request as promptly as possible so that we may complete our review.

DISTRIBUTION  
Docket Files 50-250  
and 50-251

NRC PDRs (2)  
Local PDR  
TERA  
NSIC  
NRR Reading  
ORB1 Reading  
T. Novak  
S. Varga  
M. Grotenhuis  
C. Parrish  
J. Roe  
J. Heltemes  
I&E (3)  
Attorney, OELD

Sincerely,

Original signed by:  
S. A. Varga

Steven A. Varga, Chief  
Operating Reactors Branch #1  
Division of Licensing

Enclosure:  
Request for Additional  
Information

cc: w/enclosure  
See next page

8011100548 see old yellow P

#95	OFFICE ▶ DL:ORB1	DL:ORB1	OELD			
	SURNAME ▶ MGrotenhuis;c	SAVarga	SGoldberg			
	DATE ▶ 10/11/80	10/ /80	10/ /80			

NUMBER



THE UNIVERSITY OF CHICAGO  
LIBRARY

716  
1000  
1000

Docket Nos. 50-250  
and 50-251

Dr. Robert E. Uhrig, Vice President  
Advanced Systems and Technology  
Florida Power and Light Company  
Post Office Box 529100  
Miami, Florida 33152

Dear Dr. Uhrig:

Our review of the Turkey Point Plant Steam Generator Repair Report for the Turkey Point Plant Unit Nos. 3 and 4 includes the evaluation of various alternatives for disposal of the steam generator lower assemblies. *PROPOSED* Two promising alternatives are the onsite storage and the intact shipment offsite to a licensed burial facility. We find that we need the information described in the enclosure to this letter in order to evaluate these alternatives properly. Please respond to the enclosed request as promptly as possible so that we may complete our review.

Sincerely,

Steven A. Varga, Chief  
Operating Reactors Branch #1  
Division of Licensing


Enclosure:  
Request for Additional  
Information

cc: w/enclosure  
See next page

DISTRIBUTION  
Docket Files 50-250  
and 50-251  
NRC PDRs (2)  
Local PDR  
TERA  
NSIC  
NRR Reading  
ORB1 Reading  
T. Novak  
S. Varga  
M. Grotenhuis  
C. Parrish  
J. Roe  
J. Heltemes  
I&E (3)  
Attorney, OELD  
~~XXXXXX~~

WITH NETS CHANGE

#95	OFFICE ▶	DL:ORB1	DL:ORB1	OELD ✓			
	SURNAME ▶	MGrotenhuis	bSAVarga	SGoldberg			
	DATE ▶	9/2/80	1/80	10/7/80			



Docket Nos. 50-250  
and 50-251

Dr. Robert E. Uhrig, Vice President  
Advanced Systems and Technology  
Florida Power and Light Company  
Post Office Box 529100  
Miami, Florida 33152

Dear Dr. Uhrig:

Our review of the Turkey Point Plant Steam Generator Repair Report for the Turkey Point Plant Unit Nos. 3 and 4 includes the evaluation of various alternatives for disposal of the steam generator lower assemblies. Two promising alternatives are the onsite storage and the intact shipment offsite to a licensed burial facility. We find that we need the information described in the enclosure to this letter in order to evaluate these alternatives properly. Please respond to the enclosed request as promptly as possible so that we may complete our review.

Sincerely,

Steven A. Varga, Chief  
Operating Reactors Branch #1  
Division of Licensing

Enclosure:  
Request for Additional  
Information

cc: w/enclosure  
See next page

DISTRIBUTION  
Docket Files 50-250  
and 50-251  
NRC PDRs (2)  
Local PDR  
TERA  
NSIC  
NRR Reading  
ORBT Reading  
H. Novak  
S. Varga  
M. Grotenhuis  
C. Parrish  
J. Roe  
H. Heltemes  
I&E (3)  
Attorney, OELD  
~~XXXXXX~~

OFFICE	DL:ORB1	DL:ORB1				
SURNAME	MGrotenhuis	jsAVarga				
DATE	09/2/80	/ /80				

1950

SECRET

100-361154-1  
100-361154-2  
100-361154-3  
100-361154-4  
100-361154-5  
100-361154-6  
100-361154-7  
100-361154-8  
100-361154-9  
100-361154-10  
100-361154-11  
100-361154-12  
100-361154-13  
100-361154-14  
100-361154-15  
100-361154-16  
100-361154-17  
100-361154-18  
100-361154-19  
100-361154-20

RECEIVED

APR 11 1950

MEMORANDUM  
FOR THE RECORD  
SUBJECT: [Illegible]

[Illegible text - very faint and mirrored]

[Illegible text]

[Illegible text]



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

October 21, 1980

Docket Nos. 50-250  
and 50-251

Dr. Robert E. Uhrig, Vice President  
Advanced Systems and Technology  
Florida Power and Light Company  
Post Office Box 529100  
Miami, Florida 33152

Dear Dr. Uhrig:

Our review of the Turkey Point Plant Steam Generator Repair Report for the Turkey Point Plant Unit Nos. 3 and 4 includes the evaluation of various alternatives for disposal of the steam generator lower assemblies. Two proposed alternatives are the onsite storage and the intact shipment offsite to a licensed burial facility. We find that we need the information described in the enclosure to this letter in order to evaluate these alternatives properly. Please respond to the enclosed request as promptly as possible so that we may complete our review.


Sincerely,

A handwritten signature in black ink, appearing to read "Steven A. Varga".

Steven A. Varga, Chief  
Operating Reactors Branch #1  
Division of Licensing

Enclosure:  
Request for Additional  
Information

cc: w/enclosure  
See next page





Robert E. Uhrig  
Florida Power and Light Company - 2 -

October 21, 1980

cc: Mr. Robert Lowenstein, Esquire  
Lowenstein, Newman, Reis and Axelrad  
1025 Connecticut Avenue, N.W.  
Suite 1214  
Washington, D. C. 20036

Ms. Cheryl A. Flaxman  
1023 Polk Street  
Hollywood, Florida 33019

Environmental and Urban Affairs Library  
Florida International University  
Miami, Florida 33199

Mr. Norman A. Coll, Esquire  
Steel, Hector and Davis  
1400 Southeast First National  
Bank Building  
Miami, Florida 33131

Mr. Henry Yaeger, Plant Manager  
Turkey Point Plant  
Florida Power and Light Company  
P. O. Box 013100  
Miami, Florida 33101


Mr. Jack Shreve  
Office of the Public Counsel  
Room 4, Holland Building  
Tallahassee, Florida 32304

Administrator  
Department of Environmental Regulation  
Power Plant Siting Section  
State of Florida  
2600 Blair Stone Road  
Tallahassee, Florida 32301

Resident Inspector  
Turkey Point Nuclear Generating Station  
U. S. Nuclear Regulatory Commission  
Post Office Box 971277  
Quail Heights Station  
Miami, Florida 33197

Mr. Mark P. Oncavage  
12200 S. W. 110th Avenue  
Miami, Florida 33176

Neil Chonin, Esquire  
1400 Ameri-First Building  
One Southeast Third Avenue  
Miami, Florida 33131



Enclosure

REQUEST FOR ADDITIONAL INFORMATION

DISPOSAL ALTERNATIVES

1. Describe the hurricane resisting properties of the proposed storage building for the steam generator lower assemblies.
2. Describe the procedures and methods used to assure that the inside of the steam generators remain dry while in storage.
3. Describe the transportation impacts of the shipment of the steam generator lower assemblies, including potential accidents along the route.
4. Describe the method of "sealing" the steam generator lower assemblies. In particular, the thickness, strength, etc. of the caps for the open ends of the steam generators and pipe cuts, and the geometry and dimensions of the weld joints.

