

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8012020474 DOC. DATE: 80/11/12 NOTARIZED: NO DOCKET #
 FACIL: 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PACE, P.L. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: LER 80-012/03L-0: on 801013, excessive leakage past primary packing in charging pump 4A caused pump to be removed from svc. Caused by loose packing. Packing replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR ENCL: SIZE:
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME	COPIES	
			LITR	ENCL		LITR	ENCL
	VARGA, S.	04	3	3			
INTERNAL:	A/D COMP&STRU06		1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08		1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10		1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12		1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14		1	1	AEOD	2	2
	ASLBP/J.HARD		1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16		1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18		1	1	D/DIR, HUM FAC19	1	1
	DIR, ENGINEER120		1	1	DIR, HUM FACI S21	1	1
	DIR, SYS INTEG22		1	1	EFF TR SYS BR23	1	1
	EQUIP QUALI BR25		1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29		1	1	I&E 05	2	2
	JORDAN, E./IE:		1	1	LIC GUID BR 30	1	1
	LIC QUAL BR 31		1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33		1	1	MPA	3	3
	NRC PDR 02		1	1	OP EX EVALI BR34	3	3
	OR ASSESS BR 35		1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39		1	1	REACT SYS BR 40	1	1
	REG FILE 01		1	1	RELI & RISK A 41	1	1
	SFTY PROG EVA42		1	1	STRUCT ENG BR44	1	1
	SYS INTERACI B45		1	1			
EXTERNAL:	ACRS	46	16	16	LPDR	03	1
	NSIC	05	1	1	TERA: DOUG MAY		1

DEC 3 1980

TOTAL NUMBER OF COPIES REQUIRED: LITR 69 ENCL 69

L.T.

