Docket No. 50-250 50-251

61%

MAY 3 1982

Dr. Robert E. Uhrig, Vice President Advanced Systems and Technology Florida Power and Light Company Post Office Box 529100 Miami, Florida 33152

Dear Dr. Uhrig:

On April 26, 1982, we sent you a letter regarding Control Room Habitability, Action Plan item III.D.3.4 for the Turkey Point Plant Unit Nos. 3 and 4. In this letter we requested your response to three corrective actions contained in the Draft SER enclosed. The Draft SER had been telecopied on March 25, 1982. We had a conference call for clarification purposes on April 30, 1982. In the conference call we provided clarification on item (1) Redundant dampers, and (2) Radiation monitors which we confirm in the enclosure to this letter. It is our understanding that item (3) SCUBA units is adequately covered based on your staff statements that there are three units in the control room plus five additional units within 100 feet of the control room.

Please consider this letter a clarifying supplement to our April 26, 1982 letter.

Sincerely, Original signed by: S. A. Varga

Steven A. Varga, Chief Operating Reactors Branch #1 Division of Licensing

Enclosure: As stated

cc w/encl: See next page

| .8205 PDR P | 190062 8205 ADOCK 05000 | 03 250 PDR | | | | | |
|--------------------------------|----------------------------|--|----------|------------------|-------|--------|--|
| | DL:/ORB#1 | DL:ORB#1 | | | • | | |
| OFFICE | | ······································ | <u></u> | ****** | ***** | ****** | ** |
| SURNAME 🕽 | <u>'Grotenhuis:ms</u> | savarga | | | | ••••• | ••••• |
| | 5/3/82 | (9/25/82 | | • | | | |
| .DATE 🌔 | ······ | | ******* | ***** | | 1 | |
| NRC FORM 318 (10-80) NRCM 0240 | | | OFFICIAL | CIAL RECORD COPY | | | |

Distribution: Docket File NRC PDR Local PDR ORB #1 Rdg D. Eisenhut OELD 01&E(1)MGrotenhuis ₩₩117 1982> C. Parrish NSIC ACRS (10) JHel temes

•





۵ - به همه موج

-

v_n, ∖.a.,

Robert E. Uhrig Florida Power and Light Company

cc: Mr. Robert Lowenstein, Esquire Lowenstein, Newman, Reis and Axelrad 1025 Connecticut Avenue, N.W. Suite 1214 Washington, D. C. 20036

> Environmental and Urban Affairs Library Florida International University Miami, Florida 33199

Mr. Norman A. Coll, Esquire Steel, Hector and Davis 1400 Southeast First National Bank Building Miami, Florida 33131

Mr. Henry Yaeger, Plant Manager Turkey Point Plant Florida Power and Light Company P. O. Box 013100 Miami, Florida 33101

Mr. Jack Shreve Office of the Public Counsel Room 4, Holland Building Tallahassee, Florida 32304

e.

Administrator Department of Environmental Regulation Power Plant Siting Section State of Florida 2600 Blair Stone Road Tallahassee, Florida 32301

Resident Inspector Turkey Point Nuclear Generating Station U. S. Nuclear Regulatory Commission Post Office Box 1207 Homestead, Florida 33030 James P. O'Reilly Regional Administrator - Region II U. S. Nuclear Regulatory Commission 101 Marietta Street - Suite 3100 Atlanta, Georgia 30303 ~

. х •

--

.

· ·

REQUEST FOR ADDITIONAL INFORMATION CLARIFICATION SUPPLEMENT TO THE APRIL 26, 1982 REQUEST

The fundamental requirements for control room habitability systems stems from GDC-19, "Control Room."

- 1). FP&L is considering a proposal to upgrade certain features of the ventilation systems associated with the dampers short of the installation of redundant dampers. Please provide drawings and descriptive details which completely describe and justify the proposed FP&L design.
- 2) Provide justification for a radiation detection and isolation system short of a system which includes radiation detectors, in the control room air intakes, which automatically isolates the control room. The justification should include radiation dose calculations which consider the time dependent transport of fission products into the control room prior to isolation.
- 3) Confirm the information provided by telephone on April 30, 1982, regarding SCUBA units available to the control room.

ч ~ ы. 4 — а^{ди} • • • • •

) 3.12 •

·

. . .

, , , ,

. .

•