

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9203170222 DOC. DATE: 92/03/09 NOTARIZED: NO DOCKET #
FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH. NAME AUTHOR AFFILIATION
PLUNKETT, T.F. Florida Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: Revised Emergency Plan Implementing Procedure 20106,
"Natural Emergencies." W/920309 ltr.

DISTRIBUTION CODE: A045D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 39
TITLE: OR Submittal: Emergency Preparedness Plans, Implement'g Procedures, C

NOTES: NRR RAGHAVAN, L 05000250
NRR RAGHAVAN, L 05000251

Revised 3/27/92 [Signature]

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1 1	AULUCK, R	1 1
INTERNAL:	AEOD/DOA/IRB	1 1	NRR/DREP/PEPB9D	1 1
	NUDOCS-ABSTRACT	1 1	REC FILE 01	1 1
EXTERNAL:	NRC PDR	1 1	NSIC	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 9 ENCL 9

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



MAR '09 1992

L-92-53
10 CFR 50 Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Emergency Plan Implementing Procedure


In accordance with the requirements of 10 CFR 50 Appendix E, enclosed is one copy of the following revised Emergency Plan Implementing Procedure (EPIP):

<u>Number</u>	<u>Title</u>	<u>Implementation Date</u>
20106	Natural Emergencies	02/14/92

EPIP 20106 was revised to remove the requirements of temporary flood protection for the Emergency Diesel Generator fuel oil transfer pumps. The fuel oil transfer pumps have been raised above the maximum design flood elevation specified in the Updated Final Safety Analysis Report.

Should there be any questions please contact us.

Very truly yours,


T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/OIH

enclosure

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
(2 copies)
R. C. Butcher, Senior Resident Inspector, USNRC, Turkey Point
Plant (no enclosure)

9203170222 920309
PDR ADOCK 05000250
F PDR

A045
11



11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

[Faint, illegible text covering the majority of the page]

101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150

151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200