

LICENSEE EVENT REPORT

CONTROL BLOCK: [][][][][] (1) PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION

01 3 | FIL | SL | SL | SL | SL | (2) | 0 | 0 | 0 | 1 | - | 1 | 0 | 1 | 0 | 1 | 0 | 1 | 0 | - | 1 | 0 | 1 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | 1 | 1 | (4) | | | | | (5)

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 34

01 3 | REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | (7) | 1 | 1 | 0 | 1 | 1 | 2 | 8 | 1 | 1 | (8) | 1 | 1 | 1 | 1 | 2 | 8 | 1 | 1 | (9)

20 21 22 23 24 25 26 27 28 29 30 31 32 33 34

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | DURING A REFUELING OUTAGE WHILE PERFORMING RE-TEST REQUIREMENTS FOR A

013 | PLANT MODIFICATION, THE CHANNEL "D" REFUELING WATER TANK BISTABLE WOULD

014 | NOT TRIP THE ACTUATION MODULE. THE OTHER 3 CHANNELS WERE OPERABLE. THE

015 | HEALTH AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.

015 | RAS

017 |

018 |

019 7 8 9 | SYSTEM CODE | I | B | (11) | CAUSE CODE | E | (12) | CAUSE SUBCODE | E | (13) | COMPONENT CODE | I | N | S | T | R | U | (14) | COMP. SUBCODE | X | (15) | VALVE SUBCODE | Z | (16)

9 10 11 12 13 14 15 16 17 18 19 20

(17) LEA/R0 REPORT NUMBER | 8 | 1 | (18) EVENT YEAR | 8 | 1 | (19) SEQUENTIAL REPORT NO. | 1 | 0 | 4 | 1 | (20) OCCURRENCE CODE | 0 | 3 | (21) REPORT TYPE | L | (22) REVISION NO. | 0 |

21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN | C | (23) | FUTURE ACTION | Z | (24) | EFFECT ON PLANT | Z | (25) | SHUTDOWN METHOD | Z | (26) | HOURS | 1 | 0 | 1 | 0 | 1 | 0 | (27) | ATTACHMENT SUBMITTED | N | (28) | APPROX. NORM. SUS. | N | (29) | PRIME COMP. SUPPLIER | A | (30) | COMPONENT MANUFACTURER | 0 | 5 | 6 | 1 | 0 | (31)

33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 | THE CAUSE FOR THE FAULTY BISTABLE HAS NOT YET BEEN DETERMINED. THE

111 | BISTABLE WAS REPLACED AND TESTED SATISFACTORILY.

112 |

113 |

114 |

115 7 8 9 | FACILITY STATUS | H | (32) | % POWER | 0 | 0 | 0 | (33) | OTHER STATUS | NA | (34) | METHOD OF DISCOVERY | B | (35) | DISCOVERY DESCRIPTION | TEST SURVEILLANCE | (36)

10 11 12 13 14 15 16 17 18 19 20

115 7 8 9 | ACTIVITY CONTENT | Z | (37) | Z | (38) | AMOUNT OF ACTIVITY | NA | (39) | LOCATION OF RELEASE | NA | (40)

10 11 12 13 14 15 16 17 18 19 20

117 7 8 9 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | (41) | TYPE | Z | (42) | DESCRIPTION | NA | (43)

10 11 12 13 14 15 16 17 18 19 20

118 7 8 9 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | (44) | DESCRIPTION | NA | (45)

10 11 12 13 14 15 16 17 18 19 20

119 7 8 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | (46) | DESCRIPTION | NA | (47)

10 11 12 13 14 15 16 17 18 19 20

119 7 8 9 | PUBLICITY ISSUED | Z | (48) | DESCRIPTION | NA | (49)

10 11 12 13 14 15 16 17 18 19 20

210 7 8 9 | NAME OF PREPARER | P. L. Pace | PHONE | (305) 552-3654

10 11 12 13 14 15 16 17 18 19 20

311: L00841 21112
RDA PRICR 050095
PDR

