

DEC 11 1987

Mr. J. J. Hudiburg
Chairman of the Board
Florida Power and Light Company
Post Office Box 14000
Juno Beach, Florida 33408


Dear Mr. Hudiburg:

On November 17 and 18, 1987, NRC senior managers met to review the performance of operating nuclear power plants licensed by the NRC. These meetings are conducted biannually to focus NRC resources on those plants and issues of greatest safety significance. At this meeting the Turkey Point facility was categorized as requiring continued close monitoring. NRC places plants in this category that have taken action or have committed to take action that should correct identified problems, but the effectiveness of this action has yet to be fully demonstrated. Based on being in this category, the NRC will continue to provide an increased level of headquarters and regional attention to monitoring Turkey Point's performance.

A summary of NRC discussions held relating to Turkey Point is provided below:

Turkey Point continues to experience problems in operations, engineering support, training, and security. The licensee has committed over \$700M to capital improvements (including a new simulator) and to programs that are improving performance in some areas. However, problems such as a lack of professionalism in the control room, failure to follow procedures, and poor internal communications are still occasionally evident. In apparent recognition of a lack of strong leadership at the site, a new site vice president was appointed in August. He, in turn, has made several additional management changes in key positions. In addition, he initiated a management-on-shift program in August to monitor control room operations around the clock. An instance of lack of professionalism in the control room, identified by the licensee, and other problems, led to the issuance of an NRC order on October 19 requiring the licensee to continue their management-on-shift program with specified modifications and hire an independent consulting firm to audit their operations and make recommendations for improvement. The region continues to maintain three residents on site and is now conducting monthly management meetings with the licensee to review their progress.

8712230072 871211
PDR ADOCK 05000250
P PDR



DEC 11 1987

An NRC Commission meeting open to the public has been scheduled for December 17, 1987, to review the results of the latest meeting of NRC managers. Dr. J. Nelson Grace, the Region II Administrator, has discussed the basis for our conclusions with regard to the Turkey Point facility with members of your staff.

If you have any questions regarding this matter, do not hesitate to call me.

Sincerely,

Original signed by
Victor Stello

Victor Stello, Jr.
Executive Director for Operations

DISTRIBUTION:

V Stello Jr.
JM Taylor
T Rehm

J.N. Grace, RII
Murley, NRR
TO Martin
EDO r/f
Central File
PDR
DEDRO r/f

OFC	:DEDRO	:DEDRO	:EDO	:	:	:	:
NAME	:TO Martin	:JM Taylor	:V Stello	:	:	:	:
DATE	:87/11/25	:87/11/26	:87/11/	:	:	:	:

THE UNITED STATES OF AMERICA
DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

MEMORANDUM FOR THE DIRECTOR, FBI

DATE: 10/15/68

TO: SAC, NEW YORK

FROM: SAC, NEW YORK

RE: A. R. Davis, RIII
New York, New York
10/15/68

On 10/15/68, [illegible] advised that [illegible] had been [illegible] by [illegible] on 10/15/68. [illegible] advised that [illegible] had been [illegible] by [illegible] on 10/15/68. [illegible] advised that [illegible] had been [illegible] by [illegible] on 10/15/68.

END