

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM
 REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8810120391 DOC. DATE: 88/09/28 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 HERDT, A.R. Region 2, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 CONWAY, W.F. Florida Power & Light Co.

SUBJECT: Forwards Insp Repts 50-250/88-23 & 50-251/88-23 on 880815-19
 No violations or deviations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+7
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-2 PD		1	1		EDISON, G		1	1
INTERNAL:	AEOD		1	1		DEDRO		1	1
	NRR MORISSEAU, D		1	1		NRR/DLPQ/PEB 11		1	1
	NRR/DLPQ/QAB 10		1	1		NRR/DOEA DIR 11		1	1
	NRR/DREP/EPB 10		1	1		NRR/DREP/RPB 10		2	2
	NRR/DRIS DIR 9A		1	1		NRR/PMAS/ILRB12		1	1
	NUDOCS-ABSTRACT		1	1		OE LIEBERMAN, J		1	1
	OGC/HDS2		1	1		REG-FILE 02		1	1
	RES/DSIR DEPY		1	1		RGN2 FILE 01		1	1
INTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

2

4



SEP 28 1988

Yellow

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Florida Power and Light Company
ATTN: Mr. W. F. Conway
Senior Vice President - Nuclear
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/88-23 AND 50-251/88-23

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by R. Bernhard on August 15-19, 1988. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,



Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl: (See page 2)

8810120391 880928
PDR ADOCK 05000250
Q PNU

IE 41



SEP 28 1988

Florida Power and Light Company

2

cc w/encl:

J. S. Odom, Vice President
Turkey Point Nuclear Plant
J. E. Cross, Plant Manager
Turkey Point Nuclear Plant
L. W. Bladow, Plant QA Superintendent
J. Arias, Jr., Regulatory and Compliance
Supervisor
State of Florida

bcc w/encl:

G. E. Edison, Project Manager, Project
Directorate II-2, Division of Reactor
Projects, NRR
NRC Resident Inspector
DRS Technical Assistant

RII

RBernhard:ser
09/24/88

RII

FJape
09/27/88

RII

RCrlenjak
09/26/88

