


ERATED



SYSTEM

-	4 9 33												
		.7	REGUL	ATORY	INFORM	ATION	DISTRI	BUTION SYS	STEM (F	RIDS))		
	ACCESSION NBR:8905240483 DOC.DATE: 89/05/19 NOTARIZED: NO DOCKET # FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251 AUTH.NAME AUTHOR AFFILIATION WOODY,C.O. Florida Power & Light Co.												
	Document Control Branch (Document Control Desk) R												\mathbf{R}_{\pm}
	SUBJECT: Forwards corrected "Semiannual Radioactive Effluent Release Rept,Jul-Dec 1988."												I
	DISTRIBUTION CODE: 1E48D COPIES RECEIVED:LTR / ENCL / SIZE: $1+43$												D
	TITLE: 50.36a(a)(2) Semiannual Effluent Release Reports												S
	NOTES:									•			1
		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME			COPIES LTTR ENCL			Å	
			2 LA		4 1	4 1		PD		Ļ	1		D
	INTERNAL:	AEOD/	'DSP/TPAI DREP/RPB	B 10	1	1		CH ADV 5-ABSTRACI	1 P 1		1		D
		REG	TLE	01	1 2 1 1	1 2 1 1	RGN2		3 2		2	4	S
]	EXTERNAL:	BNL T LPDR	CHLER,	J03	1 1	1 1	EG&G S NRC PI	SIMPSON, F DR	2	、 2 1	2 1	-	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

ENCL 20 20 TOTAL NUMBER OF COPIES REQUIRED: LTTR

flc-1 eet

R

I :

D


S

A

D

D

S



•



P.O. Box 14000, Juno Beach, FL 33408-0420

MAY 1 9 1989 L-89-180

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4 Docket Nos. 50-250 and 50-251 <u>Semi-Annual Radioactive Effluent Release Report</u>

By letter L-89-75 dated March 2, 1989, Florida Power & Light Company submitted the Radioactive Effluent Release Report for the period of July 1988 through December 1988 for Turkey Point Units 3 and 4, as required by Technical Specification 6.9.4.

That report stated that there had been no Offsite Dose Calculation Manual (ODCM) changes during the reporting period. No changes to the calculational methods contained in the ODCM were instituted during the period, however the ODCM was revised on August 10, 1988, to include a requirement for an annual review, as required by Technical Specification 6.8.2. Page 6 of the report has been revised to reflect this change, and pages A4-1 through A4-4 have been added to include the relevant ODCM pages.

In addition, pages 13 and 20 were revised to correct calculation errors in the "% Annual Limit" in Table 5, "Dose due to Iodine, H-3 and Particulates". Page 16 was revised to correct a typographical error.

A corrected copy of the report is attached. If you have any questions, please contact us.

Very truly yours,

0004 C. O. Woody


Acting Senior Vice President - Nuclear

COW/TCG/cm

Attachment

cc: Stewart D. Ebneter, Regional Administrator, Region II, USNRC Senior Resident Inspector, Turkey Point Plant, USNRC

8905240483 890519 PDR ADOCK 05000250



.

,

. и

.

·