

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8906200036 DOC. DATE: 89/06/01 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PEEBLES, T.A. Region 2, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 WOODY, C.O. Florida Power & Light Co.

SUBJECT: Forwards Insp Repts 50-250/89-23 & 50-251/89-23 on
 890501-05. No violations or deviations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+17
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD2-2 PD	1		1	EDISON, G	1		1
INTERNAL:	AEOD	1		1	AEOD/DEIIB	1		1
	AEOD/TPAD	1		1	DEDRO	1		1
	NRR SHANKMAN, S	1		1	NRR/DEST DIR	1		1
	NRR/DLPQ/PQEB	1		1	NRR/DOEA DIR 11	1		1
	NRR/DREP/EPB 10	1		1	NRR/DREP/RPB 10	2		2
	NRR/PMAS/ILRB12	1		1	NUDOCS-ABSTRACT	1		1
	OE LIEBERMAN, J	1		1	OGC/HDS2	1		1
	<u>REG FILE 02</u>	1		1	RGN2 FILE 01	1		1
INTERNAL:	LPDR	1		1	NRC PDR	1		1
	NSIC	1		1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 22

R
I
D
S
/
A
I
L
S



June 1, 1989

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Florida Power and Light Company
ATTN: Mr. C. O. Woody, Acting Senior
Vice President - Nuclear
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/89-23 AND 50-251/89-23

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by B. Breslau on May 1-5, 1989. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Should you have any questions concerning this letter, please contact us.

Sincerely,

(ORIGINAL SIGNED BY T. A. PEEBLES)

Thomas A. Peebles, Chief
Operations Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
K. N. Harris, Vice President
Turkey Point Nuclear Plant
J. E. Cross, Plant Manager
Turkey Point Nuclear Plant

8906200036 890601
PDR ADDCK 05000250
Q PNU

11
IE01



(cc w/encl cont'd)
L. W. Bladow, Plant QA Superintendent
K. W. Van Dyne, Regulatory and Compliance
Supervisor
State of Florida

bcc w/encl:
G. E. Edison, Project Manager, Project
Directorate II-2, Division of Reactor
Projects, NRR
NRC Resident Inspector

RII
[Signature]
BBreslau:tj
05/25/89

RII
[Signature]
PKeTogg
05/30/89

RII
[Signature]
TPeebles
05/1/89

NRR
[Signature]
DLange
05/25/89

NRR
[Signature]
GLapinsky
05/27/89

NRR
[Signature]
MMcCoy
05/25/89