Docket Nos. 50-250

and 50-251

DISTRIBUTION

Docket File NRC PDR

CParrish DMcDonald

SVarga

ORB#1 Rdg

GLainas

HThompson

MEMORANDUM FOR:

Roger D. Walker, Director

Division of Reactor Projects

Region II

FROM:

Hugh L. Thompson, Jr., Director

Division of Licensing

SUBJECT:

LICENSING ACTION REVIEWS FOR TURKEY POINT

PLANT UNITS 3 AND 4

Your assistance is requested in conducting reviews of the enclosure submittal from Florida Power and Light Company dated March 7, 1985 for Turkey Point Units 3 and 4. The product expected from you as a result of your reviews is a complete safety evaluation report suitable for use in an amendment. Your reviewers should use the Standard Review Plan (SRP) and Standard Technical Specifications (STS) as guidance in determining acceptance criteria, recognizing, of course, that for operating reactors, the criteria in these documents are not requirements.

In accordance with NRR Office Letter No. 44, each safety evaluation performed by a technical division shall have a separate SALP input provided. For purposes of this review, the Regional personnel involved are considered part of the technical divisions. Therefore, we are requesting that your forwarding memorandum contain a SALP input for the safety evaluations performed.

Work for the Turkey Point submittal concerning enriched fissionable material limits and surveillance intervals for fission detectors has been discussed with Bill Rankin of your staff. The TAC numbers for the Turkey Point review are 57119 for Unit 3 and 57120 for Unit 4. The requested completion date is April 19, 1985.

Please notify me as soon as possible if the completion date is acceptable. Any contact with the licensee concerning this review or any additional information deemed necessary should be obtained through the NRR Project Manager for Turkey Point, Dan McDonald, who can be reached at 492-7363.

Frank Miraglia/for

Hugh L. Thompson, Jr., Director Division of Licensing, NRR

Enclosure: As stated

cc w/enclosure: J. Thoma

8504020040 850321 PDR ADDCK 05000250 PDR

D. McDonald

K. Landis, RII

*See previous white for concurrence

ORB#1:DL* CParrish

3/18/85

ORB#1:DL* DMcDonald;ps

3/18/85

BC-ORB#1:DL*

SVarga 3/20/85 GLainas .

334 246 **3**

entry v at

u dhi as f

Docket Nos. 50-250

and 50-251

DISTRIBUTION

Docket File NRC PDR L PDR ORB#1 Rdg CParrish DMcDonald SVarga GLainas HThompson

MEMORANDUM FOR:

Roger D. Walker, Acting Director

Division of Project and Resident Programs

Region II

FROM:

Hugh L. Thompson, Jr., Director

Division of Licensing

SUBJECT:

LICENSING ACTION REVIEWS FOR TURKEY POINT

PLANT UNITS 3 AND 4

Your assistance is requested in conducting reviews of the submittal from Florida Power and Light Company dated March 7, 1985 for Turkey Point Units 3 and 4. The product expected from you as a result of your reviews is a complete safety evaluation report suitable for use in an amendment. Your reviewers should use the Standard Review Plan (SRP) and Standard Technical Specifications (STS) as guidance in determining acceptance criteria, recognizing, of course, that for operating reactors, the criteria in these documents are not requirements.

In accordance with NRR Office Letter No. 44, each safety evaluation performed by a technical division shall have a separate SALP input provided. For purposes of this review, the Regional personnel involved are considered part of the technical divisions. Therefore, we are requesting that your forwarding memorandum contain a SALP input for the safety evaluations performed.

Work for the Turkey Point submittal concerning enriched fissionable material limits and surveillance intervals for fission detectors has been discussed with Bill Rankin of your staff. The TAC numbers for the Turkey Point review are 57119 and 57120 for Unit 4. The requested completion date is April 19, 1985.

Please notify me as soon as possible if the completion date is acceptable. Any contact with the licensee concerning this review or any additional information deemed necessary should be obtained through the NRR Project Manager for Turkey Point, Dan McDonald, who can be reached at 492-7363.

Hugh L. Thompson, Jr., Director Division of Licensing, NRR

Enclosures: As stated

cc w/enclosures:

J. Thoma

D. McDonald

K. Landis, RII

ORB#1:DLo CParrish 3/985 ORB#1:DL DMcDonald;ps

DMcDonald;ps/ 3/4/85

BC QRB#1:DL SVavga AD-OR:DL D:DL HThompson 3/ /85 3/ /85

1. 18. The second of the secon * 9,1 N. 18 The second section is a second σ₁ κ₁ τ σ Marine Commence of the Commenc A CAR CAR STANDARD STANDARD

THE REPORT OF THE REPORT OF THE PARTY OF THE

The Barrier Company of the Begins of the sign of the s

The state of the s

Y.

Barrier Barrell

A CONTRACTOR OF THE STATE OF TH

t

The state of the s

1 1 M M M