

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company  
Turkey Point

Docket Nos. 50-250 and 50-251  
License Nos. DPR-31 and DPR-41

During the Nuclear Regulatory Commission (NRC) inspection conducted on August 25-29, 1986, a violation of NRC requirements was identified. The violation involved failure to properly implement procedures. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1986), the violation is listed below:

Technical Specification 6.8.1 requires that written procedures be implemented that meet or exceed the requirements and recommendations of USNRC Regulatory Guide 1.33.

USNRC Regulatory Guide 1.33, Appendix A, Item 6.p indicates that the forced evacuation of the control room should be covered by written procedures.

Off Normal Operating Procedure O-ONOP-103, Control Room Inaccessibility, Sections 4.5 and 5.1, require the Plant Supervisor-Nuclear to obtain and take eight (8) radios from the control room to the turbine operator shelter, distribute the radios to the specified personnel, establish communication with the operators at their local control stations, and ensure that hot standby conditions are being maintained.

Contrary to the above, on August 27, 1986, the licensee did not maintain eight (8) radios in the control room to support communications necessary to implement Off Normal Operating Procedure O-ONOP-103 in the event of control room inaccessibility. The licensee was unable to locate the full complement of eight (8) radios for approximately two days.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Florida Power and Light Company is hereby required to submit to this Office within 30 days of the date of the letter transmitting this Notice a written statement or explanation in reply including: (1) admission or denial of the violation, (2) the reason for the violation if admitted, (3) the corrective steps which have been taken and the results

8611040407 861028  
PDR ADDCK 05000250  
Q PDR

MEMORANDUM

DATE: 11/15/50

TO: SAC, NEW YORK (100-100000)

FROM: SA [Name], NEW YORK

SUBJECT: [Subject]

Reference is made to [Subject]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

100-100000-1000

Florida Power and Light Company  
Turkey Point

2 Docket Nos. 50-250 and 50-251  
License Nos. DPR-31 and DPR-41

achieved, (4) the corrective steps which will be taken to avoid further violations, and (5) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

FOR THE NUCLEAR REGULATORY COMMISSION

Roger D. Walker, Director  
Division of Reactor Projects

Dated at Atlanta, Georgia  
this 28 day of October 1986

1. The first part of the document is a list of names and addresses.

2. The second part of the document is a list of names and addresses.

3. The third part of the document is a list of names and addresses.

4. The fourth part of the document is a list of names and addresses.

5. The fifth part of the document is a list of names and addresses.

