

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8903280104 DOC. DATE: 89/03/23 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 CONWAY, W.F. Florida Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890109, breached fire barriers & other fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD2-2 LA	1		1	PD2-2 PD	1		1
	EDISON, G	1		1				
INTERNAL:	ACRS MICHELSON	1		1	ACRS MOELLER	2		2
	ACRS WYLIE	1		1	AEOD/DOA	1		1
	AEOD/DSP/TPAB	1		1	AEOD/ROAB/DSP	2		2
	DEDRO	1		1	IRM/DCTS/DAB	1		1
	NRR/DEST/ADE 8H	1		1	NRR/DEST/ADS 7E	1		0
	NRR/DEST/CEB 8H	1		1	NRR/DEST/ESB 8D	1		1
	NRR/DEST/ICSB 7	1		1	NRR/DEST/MEB 9H	1		1
	NRR/DEST/MTB 9H	1		1	NRR/DEST/PSB 8D	1		1
	NRR/DEST/RSB 8E	1		1	NRR/DEST/SGB 8D	1		1
	NRR/DLPQ/HFB 10	1		1	NRR/DLPQ/QAB 10	1		1
	NRR/DOEA/EAB 11	1		1	NRR/DREP/RAB 10	1		1
	NRR/DREP/RPB 10	2		2	NRR/DRIS/SIB 9A	1		1
	NUDOCS-ABSTRACT	1		1	<u>REG FILE</u> 02	1		1
	RES/DSIR/EIB	1		1	RES/DSR/PRAB	1		1
	RGN2 FILE 01	1		1				
EXTERNAL:	EG&G WILLIAMS, S	4		4	FORD BLDG HOY, A	1		1
	H ST LOBBY WARD	1		1	LPDR	1		1
	NRC PDR	1		1	NSIC MAYS, G	1		1
	NSIC MURPHY, G.A	1		1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 45 ENCL 44

I/A-2

R
I
D
S
/
A
D
S
/
A
D
D
S



MARCH 23 1989

L-89-114

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

W. F. Conway
Senior Vice President - Nuclear

WFC/RHF/gp

Attachment

cc: Malcolm L. Ernst, Acting Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8903280104 890323
PDR ADOCK 05000250
S PDC

IE22
11

SPECIAL REPORT

MARCH 23, 1989

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

Fire Protection Impairment (FPI) 2292 was opened for grout repair on penetrations 108AF-E002, 108AF-E003 and 108AF-E004. FPI 2297 was opened for a void in barrier 070N. FPI 2298 is for a breach of barrier 106W. FPI 2300 on barrier 054F was opened for access in support of construction work. FPI 2301 is for voids around fire damper 43A in barrier 045W2. FPI 2302 is for voids around fire damper 44A in barrier 045N2. FPI 2304 was opened for a pipe reroute through barrier 045S.

CAUSE AND CORRECTIVE ACTIONS:

FPI's 2300 and 2304 were opened for plant modifications. FPI's 2292, 2297, 2298, 2301 and 2302 were opened for existing plant conditions found during a barrier surveillance. Detector operability was verified and fire watch patrols were established. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

FPI 2190, reported as open in FPL letter L-89-012, dated January 9, 1989, was closed on February 4, 1989. FPI 2162, reported as open in FPL letter L-89-012, was closed on February 22, 1989. FPI 1882, reported as open in FPL letter L-88-471, dated October 10, 1988, was closed on February 24, 1989. FPI 1573, reported as open in FPL letter L-88-251, dated June 06, 1988, was closed on February 19, 1989. FPI 1347, reported as open in FPL letter L-88-163, dated April 04, 1988, was closed on February 2, 1989.

