## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8904120248 DOC.DATE: 89/03/30 NOTARIZED: NO DOCKET # FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251 AUTH.NAME AUTHOR AFFILIATION CRLENJAK,J. Region 2, Ofc of the Director RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: PNO-II-89-028:during wks of 890313 & 20,NRC administered requalification exams to 24 licensed operators at plant.

DISTRIBUTION CODE: IE34D COPIES RECEIVED:LTR O ENCL SIZE:

TITLE: Preliminary Notification-Occurrence/Non-Routine Event/Safeguards Even S

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	A
INTERNAL:	ACRS/SIESS NRC OP CNTR	1 1	AEOD/DSP/TPAB NRR/DRIS/SGB 9A	1 1	D
	NRR/DRIS/SIB 9A NRR/PMAS/ILRB12	1 1	NRR/DRIS/VIB NUDOCS-ABSTRACT		D
	OE LIEBERMAN,J RES BROOKS,B	1 1	REG FILE 02 RES DEPY	1 1 1 ·	S
	RES FILE RES/DRA	1 1	RES/DE RES/DSIR	1 1	
	RES/DSIR/EIB RES/PMPDAS	1 1	RES/DSR DEPY RGN2 FILE 01	1 1	
EXTERNAL:	DOE BARBER EV34 NRC PDR	1 1	LPDR NSIC	1 1	
	111.0 1 21.	7 -		4 –	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

Alo-Y

R

R

March 30, 1989

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-89-28

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

ACILITY: Florida Power and Light Company Turkey Point Units 3, 4 Docket No. 50-250, 50-251		Licensee Emergency Classification  Notification of Unusual Even Alert Site Area Emergency	
•		General Emergency X Not Applicable	

SUBJECT: OPERATOR REQUALIFICATION EXAMINATIONS AT TURKEY POINT

During the weeks of March 13 and 20, 1989, the NRC administered requalification examinations to 24 licensed operators at the Turkey Point plant. Preliminary results are that at least 3 of 6 crews and 11 of 24 individuals have failed the exams. FPL has agreed to shut down Unit 3 while restructuring the operating crews with only those personnel who have recently demonstrated competence to the NRC. Additionally, they have agreed to conduct, prior to unit startup, an assessment of these crews on the simulator to ensure that the restructured crew complement performs effectively. The NRC will observe these assessments prior to unit startup. A meeting was held between the NRC and the licensee on March 29, 1989, and a letter issued on March 30, 1989, confirming the licensee's compensatory actions. Unit 3 was shut down on the evening of March 29, 1989. Unit 4 is currently in a refueling outage.

The State of Florida has been informed.

Media interest has been shown.

CONTACT: J. Crlenjak - 242-5097

## DISTRIBUTION:

One White Flint North Chairman Zech	M'land Nat'l <u>Bank Bldg</u> ARM	<u>Regions</u> Region I	MAIL TO:	DCS (Original IE 34) DOT (Transportation Only)
Comm. Roberts Comm. Carr Comm. Rogers Comm. Curtiss	- OIA AEOD	Region II Region III Region IV Region V	FAX TO:	INPO /:50 LICENSEE (Corporate) <b>Z:65</b> RII Resident /:55
SECY OGC OCA GPA/SLITP/PA	Nicholson Lane RES		•	•
EDO OI	H Street .			·

NRR ACRS NMSS PDR

5520: 03/30/89 @ 12:45 p.m. TO REGIONS AND HQ

8904120248 890330 PDR I&E PNO-II-89-028 PDC IE-34/ DMB 0/1