

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8907200188 DOC. DATE: 89/07/06 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 EDISON, A.F. Region 2, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 WOODY, C.O. Florida Power & Light Co.

SUBJECT: Forwards Insp Repts 50-250/89-29 & 50-251/89-29 on 890619-23. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 279
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	PD2-2	PD	1	1	EDISON, G		1	1
INTERNAL:	AEOD		1	1	AEOD/DEIIB		1	1
	AEOD/TPAD		1	1	DEDRO		1	1
	NRR SHANKMAN, S		1	1	NRR/DEST DIR		1	1
	NRR/DLPQ/PEB		1	1	NRR/DOEA DIR 11		1	1
	NRR/DREP/EPB 10		1	1	NRR/DREP/RPB 10		2	2
	NRR/PMAS/ILRB12		1	1	NUDOCS-ABSTRACT		1	1
	OE LIEBERMAN, J		1	1	OGC/HDS2		1	1
	<u>REG-FILE</u> 02		1	1	RES MORISSEAU, D		1	1
	RGN2 FILE 01		1	1				
EXTERNAL:	LPDR		1	1	NRC PDR		1	1
	NSIC		1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 23

R
I
D
S
/
A
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

July 6, 1989

Yellow

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Florida Power and Light Company
ATTN: Mr. C. O. Woody, Acting
Senior Vice President - Nuclear
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/89-29 AND 50-251/89-29

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by William P. Kleinsorge, P.E., on June 19-23, 1989. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved item identified in the Inspection Report. This matter will be pursued during future inspections.

The enclosed Inspection Report documents an oral commitment (see paragraphs 2b(3) and 2c(2)) made by a licensee representative and discussed in the exit interview. If your understanding of this commitment differs from the report statements, please inform this office promptly.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

B907200188 B90706
PDR ADCK 05000250
Q PNU

IE01 8/10



July 6, 1989

Florida Power and Light Company

2

Should you have any questions concerning this letter, please contact us.

Sincerely,

original signed by
Albert F. Gibson

Albert F. Gibson, Director
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
K. N. Harris, Vice President
Turkey Point Nuclear Plant
J. E. Cross, Plant Manager
Turkey Point Nuclear Plant
L. W. Bladow, Plant QA Superintendent
E. Lyons, Acting Regulatory and
Compliance Supervisor
State of Florida

bcc w/encl:
G. E. Edison, Project Manager, Project
Directorate II-2, Division of Reactor
Projects, NRR
NRC Resident Inspector

RII:DRS
WKleinsorge:ser
06/29/89

RII:DRS
RPC
RCarrion
06/29/89

RII:DRS
JFlake
06/30/89

RII:DRS
CX
CJulian
06/1/89
7/3/89

RII:DRP
KFor
RCrlenjak
06/3/89
7

