-ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

R

1

D

D

R

ACCESSION NBR:8908100285 DOC.DATE: 89/07/31 NOTARIZED: NO DOCKET #
FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
AUTH.NAME AUTHOR AFFILIATION
STOHR,J.P. Region 2, Ofc of the Director
RECIP.NAME RECIPIENT AFFILIATION
WOODY,C.O. Florida Power & Light Co.

SUBJECT: Forwards Insp Repts 50-250/89-31 & 50-251/89-31 on 890710-14. No violations or deviations noted.


DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR / ENCL / SIZE: 2 + >
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME PD2-2 PD	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME EDISON,G	COP: LTTR 1	IES ENCL 1	
INTERNAL:	AEOD AEOD/TPAD NRR SHANKMAN,S NRR/DLPQ/PEB NRR/DREP/EPB 10 NRR/PMAS/ILRB12 OE LIEBERMAN,J REG FILE 02 RGN2 FILE 01	1 1 1 1 1 1	1 1 1 1 1 1 1 1 1	AEOD/DEIIB DEDRO NRR/DEST DIR NRR/DOEA DIR 11 NRR/DREP/RPB 10 NUDOCS-ABSTRACT OGC/HDS2 RES MORISSEAU, D	1 1 2 1 1	1 1 1 2 1 1	1
EXTERNAL:	LPDR NSIC	1	1	NRC PDR	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23



Docket Nos. 50-250, 50-251 License Nos. DPR-31, DPR-41

Florida Power and Light Company
ATTN: Mr. C. O. Woody, Acting
Senior Vice President - Nuclear
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/89-31 AND 50-251/89-31

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by J. L. Kreh on July 10-14, 1989. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,


DESCRIPTION OF THE STATE OF THE

↓OC J. Philip Stohr, Director Division of Radiation Safety and Safeguards

Enclosure: NRC Inspection Report

cc w/encl: (See page 2)

8908100285 890731 PDR ADOCK 05000250 Q PDC IEO)



cc w/encl:

K. N. Harris, Vice President
Turkey Point Nuclear Plant
J. E. Cross, Plant Manager
Turkey Point Nuclear Plant
L. W. Bladow, Plant QA Superintendent
E. Lyons, Acting Regulatory and

Compliance Supervisor

bcc w/encl:

State of Florida

G. E. Edison, Project Manager, Project
Directorate II-2, Division of Reactor
Projects, NRR
NRC Resident Inspector
Document Control Desk
W. D. Travers, NRR/EPB
J. C. Heard, Jr., FEMA RIV

RIII: DRSS UKreh 7/28/89 RII:DRSS WRankin 7/28/89 RII: DRSS DCollins 7/28/89

RIM: DRP ROTTenjak 7-18/89

