

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8909080134      DOC. DATE: 89/08/23      NOTARIZED: NO      DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C      05000250  
       50-251 Turkey Point Plant, Unit 4, Florida Power and Light C      05000251  
 AUTH. NAME                      AUTHOR AFFILIATION  
 GIBSON, A.F.                      Region 2, Ofc of the Director  
 RECIP. NAME                      RECIPIENT AFFILIATION  
 WOODY, C.O.                      Florida Power & Light Co.

SUBJECT: Forwards Insp Repts 50-250/89-32 & 50-251/89-32 on  
 890626-30. No violations or deviations noted.

DISTRIBUTION CODE: IE01D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 2 + 14  
 TITLE: General (50 Dkt) - Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES LTR	ENCL
	PD2-2 PD	1	1	EDISON, G	1	1
INTERNAL:	AEOD	1	1	AEOD/DEIIB	1	1
	AEOD/TPAD	1	1	DEDRO	1	1
	LOIS, ERASMIA	1	1	NRR SHANKMAN, S	1	1
	NRR/DEST DIR	1	1	NRR/DLPQ/PEB	1	1
	NRR/DOEA DIR 11	1	1	NRR/DREP/EPB 10	1	1
	NRR/DREP/RPB 10	2	2	NRR/PMAS/ILRB12	1	1
	NUDOCS-ABSTRACT	1	1	OE LIEBERMAN, J	1	1
	OGC/HDS2	1	1	<del>REG-FILE</del> 02	1	1
	RES MORISSEAU, D	1	1	RGN2 FILE 01	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTR 24 ENCL 24

R  
I  
D  
S  
/  
A  
D  
S  
  
  
  
  
  
  
  
  
  
  
  
R  
I  
D  
S  
/  
A  
D  
S



August 23, 1989

yellow

Docket Nos. 50-250, 50-251  
License Nos. DPR-31, DPR-41

Florida Power and Light Company  
ATTN: Mr. C. O. Woody, Acting  
Senior Vice President - Nuclear  
P. O. Box 14000  
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-250/89-32 AND 50-251/89-32

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by P. T. Burnett on June 26-30, 1989. The inspection included a review of activities authorized for your Turkey Point facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter; please contact us.

Sincerely,  
original signed by  
Albert F. Gibson

Albert F. Gibson, Director  
Division of Reactor Safety

Enclosure:  
NRC Inspection Report

cc w/encl: (See page 2)

8909080134 890823  
PDR ADDCK 05000250  
Q FDC

11  
ZED

August 23, 1989

Florida Power and Light Company

2

cc w/encl:

K. N. Harris, Vice President  
Turkey Point Nuclear Plant  
J. E. Cross, Plant Manager  
Turkey Point Nuclear Plant  
L. W. Bladow, Plant QA Superintendent  
E. Lyons, Acting Regulatory and  
Compliance Supervisor  
State of Florida

bcc w/encl:

G. E. Edison, Project Manager, Project  
Directorate II-2, Division of Reactor  
Projects, NRR  
NRC Resident Inspector  
G. Belisle  
R. Crlenjak  
P. Burnett

RII:DRS  
*PTB*  
PTBurnett:er  
08/18/89

RII:DRS  
*edw*  
GABelisle  
08/21/89

RII:DRP  
*msc for*  
RVCrlenjak  
08/21/89

RII:DRS  
*AM*  
CJuTian  
08/21/89

