ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9006260053 DOC.DATE: 90/06/19 NOTARIZED: YES DOCKET #
FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C
AUTH.NAME AUTHOR AFFILIATION
GOLDBERG,J.H. Florida Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Final Rept of ISI NDE of Unisolable Piping Sys & Components for Potential Thermal Stress Effects...."

DISTRIBUTION CODE: IE16D COPIES RECEIVED:LTR \perp ENCL \perp SIZE: 2+120 TITLE: Bulletin Response 88-08 - Thermal Stress in Piping to RCS.

NOTES:

•	RECIPIENT ID CODE/NAME PD2-2 LA EDISON,G	COPIE LTTR 1 1		RECIPIENT ID CODE/NAME PD2-2 PD	COPI LTTR 1	_ -
INTERNAL:	AEOD/DOA NRR HARTZMAN,M NRR MOZAFARI,B NRR/DOEA/OEAB11 NRR/DREP/PEPB9D NRR/PMAS/ILRB12 RES/DSIR/EIB	1 1 1 1 1	1 1 1 1 1 1	AEOD/DSP/TPAB NRR HUM, M NRR/DET/EMEB9H3 NRR/DOEA/OGCB11 NRR/DST/_8E2 REG_EILE 02 RGN2 FILE 01	1 1 1 1 1	1 1 1 1 1
EXTERNAL:	LPDR NSIC	1	1	NRC PDR	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 19

ته پرورورونځان و تر ولیځو دی وځې و درونځ کړ . مرکاڅو ده . د په کارځ ده . د بهله مرمولځو د تا کام لاکاومه

may

R I

D

R

D

D

S

s /

A, D

D

D D





L-90-226

U. S. Nuclear Regulatory Commission

Attn: Document Control Desk Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4

Docket Nos. 50-250 and 50-251

NRC Bulletin 88-08

Thermal Stresses in Piping

Connected to Reactor Coolant Systems

NRC Bulletin 88-08, "Thermal Stresses in Piping Connected to Reactor Coolant Systems", dated June 22, 1988, requested that licensees (1) review their reactor coolant systems (RCS) to identify any connected, unisolable piping that could be subjected to temperature distributions which would result in unacceptable thermal stresses, and (2) take action, where such piping is identified, to ensure that the piping will not be subjected to unacceptable thermal stresses.

By letter L-88-436 dated October 14, 1988, Florida Power & Light Company (FPL) responded to action items 1 and 2 of the bulletin, providing the results of our review for Turkey Point Units 3 and 4, and a plan and schedule for completing the non-destructive examination (NDE) required by the bulletin.

By letter L-89-176 dated May 4, 1989, FPL provided the NDE results for Turkey Point Unit 4, and also, the results of a flow evaluation which concluded that the conditions described in NRC Bulletin 88-08 are not likely to occur at Turkey Point.

The NDE of Turkey Point Unit 3 has been completed. No crack indications were observed. A report of the examination is attached.

This completes the actions required by the bulletin. As stated in our May 4, 1989 letter, FPL will again examine this piping during the next refueling outage for each unit.

Should there be any questions, please contact us.

Very truly yours,

J. H. Goldberg

President


Nuclear Division

9006260053 900619 PDR ADOCK 05000250

Attachments

cc: Stewart D. Ebneter, Regional Administrator, Region II, USNRC Senior Resident Inspector, USNRC, Turkey Point Plant

an FPL Group company



STATE OF FLORIDA) ss.
COUNTY OF PALM BEACH)

J. H. Goldberg being first duly sworn, deposes and says:

That he is <u>President</u>, <u>Nuclear Division</u>, of Florida Power and Light Company, the Licensee herein;

That he has executed the foregoing document; that the statements made in this document are true and correct to the best of his knowledge, information and belief, and that he is authorized to execute the document on behalf of said Licensee.

J. H. Goldberg

Subscribed and sworn to before me this

 $\frac{19}{2}$ day of $\frac{90}{2000}$, $\frac{90}{2000}$

NOTARY PUBLIC, in and for the County of Palm Beach, State of Florida

My commission expires

My Commission Expires June 1, 1993

