

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9008270168    DOC.DATE: 90/08/16    NOTARIZED: NO    DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C    05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C    05000251

AUTH.NAME                      AUTHOR AFFILIATION  
 HARRIS, K.N.                  Florida Power & Light Co.  
 RECIPIENT NAME              RECIPIENT AFFILIATION  
                                  Document Control Branch (Document Control Desk)

SUBJECT: Special rept re breached fire barriers & other fire protection sys impairments, per Tech Spec 6.9.3.c. Fire protection impairments issued for support of backfit. const work. Util continues to implement compensatory measures.

DISTRIBUTION CODE: IE22D    COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-2 LA EDISON, G	1 1	PD2-2 PD	1 1
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB9H3	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	<u>REG FILE</u> 02	1 1	RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	EG&G BRYCE, J.H	3 3	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MAYS, G	1 1
	NSIC MURPHY, G.A	1 1	NUDOCS FULL TXT	1 1

*2nd Dist  
 Previously  
 Processed under  
 incorrect Rids  
 Code*

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 31 ENCL 31

*IA 2  
 int*



AUG 16 1990

L-90-302

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Special Report - Breached Fire Barriers and  
Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,

  
K. N. Harris  
Plant Vice President  
Turkey Point Plant Nuclear

KNH/JEK/jk

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II,  
USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

9008270168 900816  
PDR ADOCK 05000250  
S PIC

00051

(2nd Dist)  
Reviewed under  
measur R125  
Code  
A006  
1/1

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

See attached list for Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPIs 3438, 3446, 3459, 3462 and 3463 were issued for support of backfit construction work. Turkey Point continues to implement the compensatory measures as applicable.

STATUS UPDATE:

Please refer to the attached list for Fire Protection Impairments that were previously reported and are now closed.

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT  
WHICH HAVE BEEN OPEN LONGER THAN TECH. SPEC. LIMITS

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3438	Door 25-1	07/03/90	
3446	Structural Steel 025C	07/09/90	
3459	Barrier Thermolag 3A1394	07/19/90	08/03/90
3462	Door 25-2	07/23/90	
3463	Detector Alarm PT.35	07/23/90	

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY  
NOT REPORTED CLOSED

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER &amp; DATE</u>	
1766	Penetration 045F-M013	07/17/90	L-88-535	12/16/88
1805	Penetration 014N-M017	07/31/90	L-88-383	08/29/88
2665	Structural Steel 062	08/10/90	L-89-333	09/14/89
2810	Penetration 067S-M004	07/20/90	L-89-375	10/30/89
3279	Penetration 055N-M006	07/17/90	L-90-139	04/17/90
3366	Structural Steel 058C	07/27/90	L-90-185	05/18/90
3411	Detector 39-12,14 & 15	08/08/90	L-90-267	07/17/90

