

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9111190140 DOC. DATE: 91/11/12 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co. *Revised 1/24/92 CEC*
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards Rev 23 to Radiological Emergency Plan. Revised EPIPs
 20101, 20104, 20110 & 20127 also encl.

DISTRIBUTION CODE: A045D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 260
 TITLE: OR Submittal: Emergency Preparedness Plans, Implement'g Procedures, c

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
	PD2-2	PD	1	1	AULUCK,	R	1	1
INTERNAL:	AEOD/DOA/IRB		1	1	<u>NRR/DREP/PEPB9D</u>		1	1
	NUDOCS-ABSTRACT		1	1	<u>REG FILE</u>	01	1	1
EXTERNAL:	NRC	PDR	1	1	NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 8 ENCL 8

MAY

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



NOV 12 1991

L-91-305

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Emergency Plan Implementing Procedures and
Radiological Emergency Plan - Revision 23

Florida Power and Light Company (FPL) has issued Revision 23 to the Turkey Point Radiological Emergency Plan and has determined that the revision does not decrease the effectiveness of the plan. The Emergency Classification Tables have been revised to reflect enhanced administrative controls and to provide clarification of Emergency Action Level terminology as a result of feedback from Licensed Operator Continuing Training. Pursuant to 10 CFR 50.54 (q), one copy of the plan is enclosed.

Also enclosed in accordance with the requirements of 10 CFR 50 Appendix E, is one copy each of the following revised Emergency Plan Implementing Procedures (EPIPs):


<u>Number</u>	<u>Title</u>	<u>Implementation Date</u>
20101	Duties of Emergency Coordinator	October 21, 1991
20104	Duty Call Notifications/ Staff Augmentation	October 28, 1991
20110	Criteria For and Conduct of Owner Controlled Area Evacuation	October 28, 1991
20127	Duties of the Offsite Assembly Area Supervisor	October 28, 1991

152034

9111190140 911112
PDR ADOCK 05000250
F PDR

an FPL Group company

ADK 1/1



EPIP 20101 has been updated to reflect changes to the Emergency Plan. These changes consisted of reorganization of procedural steps for a Site Area Emergency, addition of sigma theta and delta T information, and performance of release calculations during any release. EPIP 20104 has been updated to reflect enhanced notification instructions. EPIP 20110 has been updated to clarify evacuation criteria and to provide more readable maps. EPIP 20127 has been updated to correct position titles and to provide more readable maps. EPIPs 20113 and 20119 have been cancelled, with the information incorporated into a plant administrative procedure.

Should there be any questions please contact us.

Very truly yours,



T. F. Plunkett
Vice President
Turkey Point Nuclear

TFP/OIH

enclosure

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC (2
copies)
Senior Resident Inspector, USNRC, Turkey Point Plant
(no enclosure)