

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM
REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210050254 DOC. DATE: 92/09/29 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 GOLDBERG, J.H. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that implementation of seismic program to address
 Suppl 4 to GL 88-20 re IPE of external events for severe
 accident vulnerabilities, delayed from Sept 1992 due to
 competing resources as result of Hurricane Andrew.

DISTRIBUTION CODE: A011D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Generic Ltr 88-20 re Individual Plant Evaluations

NOTES: NRR RAGHAVAN, L 05000250
 NRR RAGHAVAN, L 05000251

	RECIPIENT	COPIES		RECIPIENT	COPIES
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR
					ENCL
	PD2-2 PD	1	1	AULUCK, R	1
INTERNAL:	ACRS HOUSTON, M	1	1	AEOD/DSP/TPAB	1
	NRR HERNAN, R	1	1	NRR/DREP/PRAB	1
	REG 1	1	1	REG 2	1
	REG 3	1	1	REG 4	1
	REG FILE	1	1	RES FLACK, J	3
	RES MITCHELL, J	1	1	RES/DSIR/SAIB/B	7
EXTERNAL:	NRC PDR	1	1	NSIC	1
NOTES:		1	1		


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25 ⁰

MR. [Signature]

R
I
D
S
/
A
D
D
S
/
A
D
D
S
/
A
D
D
S
/
A
D
D
S





FPL

SEP 29 1992

L-92-279

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 and 50-251
St. Lucie Units 1 and 2
Individual Plant Examination of
External Events (IPEEE) for
Severe Accident Vulnerabilities
Generic Letter (GL) No. 88-20, Supplement 4

Florida Power and Light Company (FPL), by letter dated August 31, 1992, indicated that it would be implementing the FPL Seismic Program at St. Lucie Unit 2 in September 1992. Due to competing resource needs to support the recovery program at Turkey Point after Hurricane Andrew, the implementation has been delayed and will now occur prior to the end of 1992.

Very truly yours,

J.H. Goldberg
President
Nuclear Division

JHG/REG/vmg

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant
Senior Resident Inspector, USNRC, St. Lucie Plant

9210050254 920929
PDR ADDCK 05000250
P PDR

AO 11-1/0



Handwritten scribbles in the top right corner.

Handwritten scribbles at the bottom right corner.