ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

R

Ι

D

S

D

D


S

			€	•	
ACCESSION FACIL: 50 AUTH: NA PLUNKET RECIP: 1	N NBR:9305140226 0-250 Turkey Point AME AUTHOR T,T.F. Florida NAME RECIPIE ,S.D. Region 2	Plant, Unit AFFILIATION Power & Light NT AFFILIATIO	ОИ): NO and Light C	05000250 .R
	plugged as resul	t of insp.	of 930424-28 insp	•	I D
DISTRIB	UTION CODE: A001D OR Submittal: Gene	COPIES RECEI ral Distribut	EVED:LTR \perp ENCL O	SIZE:	s
NOTES:					1
	RECIPIENT ID CODE/NAME PD2-2 LA RAGHAVAN,L		RECIPIENT ID CODE/NAME PD2-2 PD	COPIES LTTR ENCL	A D
INTERNAL:	NRR/DE/EELB NRR/DRCH/HICB NRR/DSSA/SPLB NUDOCS-ABSTRACT OGC/HDS3	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NRR/DORS/OTSB NRR/DSSA/SCSB NRR/DSSA/SRXB OC/LEMB REG FILE 01	1 1 1 0 1 1 1 0	D S
EXTERNAL:	NRC PDR	1	NSIC	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

16 ENCL 13-0 TOTAL NUMBER OF COPIES REQUIRED: LTTR





MAY 04 1993

L-93-128 10 CFR 50.36

Stewart D. Ebneter Regional Administrator U. S. Nuclear Regulatory Commission 101 Marietta Street, N.W., Suite 2900 Atlanta, Georgia 30323

Dear Mr. Ebneter:

Re: Turkey Point Unit 4
Docket No. 50-250

Steam Generator Tube Plugging

The Turkey Point Unit 4 steam generators were inspected from April 24, 1993 through April 28, 1993. There were no steam generator tubes plugged as a result of this inspection. This letter meets the requirements of notification in accordance with Technical Specification 4.4.5.5.

Should there be any questions, please contact us.

Very truly yours,

T. F. Plunkett

Vice President

Turkey Point Nuclear

TFP/OIH

cc: USNRC, Document Control Desk, Washington, D.C. R. C. Butcher, Senior Resident Inspector, USNRC, Turkey Point Plant

9305140226 930504 PDR ADDCK 05000250 P PDR 100/ 100/