

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION # BR: 9312030068 DOC. DATE: 93/11/24 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 GOLDBERG, J. H. Florida Power & Light Co.
 RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that util intends to dissolve Safety Engineering Group by year end to eliminate duplication in effort.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTTR	ENCL	
	PD2-2 LA	1	1		PD2-2 PD	1	1		A
	RAGHAVAN, L	2	2						D
INTERNAL:	NRR/DE/EELB	1	1		NRR/DORS/OTSB	1	1		D
	NRR/DRCH/HICB	1	1		NRR/DSSA/SPLB	1	1		
	NRR/DSSA/SRXB	1	1		NUDOCS-ABSTRACT	1	1		S
	OC/LFDGB	1	0		OGC/HDS3	1	0		
	<u>REG FILE</u> 01	1	1						
EXTERNAL:	NRC PDR	1	1		NSIC	1	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-3/ (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTTR 15 ENCL ~~13~~ 0



NOV 24 1993

L-93-268

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Subject: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Independent Safety Engineering Group

The purpose of this letter is to inform you of our intention to change a previous commitment regarding the establishment of a Turkey Point Safety Engineering Group (SEG).

On April 11, 1984, FPL transmitted a letter from J. W. Williams, Jr. (FPL) to J. P. O'Reilly (USNRC). The purpose of that letter was to outline numerous performance enhancement initiatives at FPL that were being put in place to address Turkey Point's marginal regulatory performance. Included in those initiatives was a commitment to set up a small Safety Engineering Group which would provide additional oversight on plant operating issues and root cause evaluations.

Since that time, FPL has embodied strong independent review of plant operating conditions and enhanced root cause analysis techniques within other Turkey Point nuclear organizations. To eliminate this duplication of effort, it is our intent to dissolve the SEG group by the end of this year.

The Vice President of Nuclear Assurance will be responsible for closely and independently monitoring site activities regarding this commitment change to ensure that there is continued high quality in Turkey Point's regulatory performance.

If you have any questions regarding our plans in this area, please contact me.

Very truly yours,

J. H. Goldberg
President
Nuclear Division

cc: S. D. Ebnetter, Regional Administrator, Region II, USNRC
T. P. Johnson, Senior Resident Inspector, USNRC, Turkey Point Plant

9312030068 931124
PDR ADDCK 05000250
P PDR

ADD 1/0

0001 0002

0003 0004

0005 0006