



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
1600 EAST LAMAR BLVD  
ARLINGTON, TEXAS 76011-4511

## EMAIL



**Name:** Rick Donaldson, Vice President  
Lance Bowser, RSO License: 25-19316-01  
**Organization:** Robert Peccia & Associates, Inc. Docket: 030-17419  
**Phone:** 406-447-5000 Control: 601587  
**E-mail Address:** [rdonaldson@rpa-hln.com](mailto:rdonaldson@rpa-hln.com)  
[lbowser@rpa-hln.com](mailto:lbowser@rpa-hln.com)  
**From:** Jacqueline D. Cook  
**Date:** December 27, 2017  
**Subject:** Letter dated October 27, 2017 for License Amendment  
**Pages:** 2

Mr. Donaldson & Mr. Bowser:

Per your letter dated October 27, 2017, the item on the next page is a deficiency which requires your response. **Please respond to this e-mail by Wednesday, January 10, 2018.** Our fax number is (817) 200-1263. **Please provide a response in a signed and dated letter in pdf format when responding via email.** My email address is [Jackie.Cook@nrc.gov](mailto:Jackie.Cook@nrc.gov). When responding to this e-mail, please include the license, docket, and control numbers located at the top of this page.

Thanking you in advance for your cooperation, assistance, and prompt response in this matter.

*/RA/*

Jacqueline D. Cook  
Senior Health Physicist

**PUBLIC**

- Immediate Release  
 Normal Release

**NON-PUBLIC**

- A.3 Sensitive-Security Related  
 A.7 Sensitive Internal  
 Other:

Reviewer: JDC Date: 12/27/17

R. Donaldson  
L. Bowser

-2-

1. In order to remove the old/previous storage locations specified in Item 10.A. for unrestricted use, please submit a copy(ies) of the latest leak test result(s) and a statement that "no leaking sources have ever been identified" while stored at this storage location.