

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8709140201 DOC. DATE: 87/09/08 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 AUTH. NAME AUTHOR AFFILIATION
 HERDT, A. R. Region 2, Office of Director
 RECIP. NAME RECIPIENT AFFILIATION
 UTLEY, E. E. Carolina Power & Light Co.

SUBJECT: Forwards Insp Rept 50-400/87-32 on 870810-14. No violations or deviations noted. Understands that loss of 100% electric load test to be performed no later than 871130 & will be performed per FSAR 14.2.12.2.18 & Reg Guide 1.68.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+14
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: Application for permit renewal filed.

05000400

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	BUCKLEY, B	2 2
INTERNAL:	AEOD	1 1	DEDRO	1 1
	NRR MORISSEAU, D	1 1	NRR/DOEA DIR	1 1
	NRR/DREP/EPB	1 1	NRR/DREP/RPB	2 2
	NRR/DRIS DIR	1 1	NRR/PMAS/ILRB	1 1
	GE, LIEBERMAN, J	1 1	OGC/HDS1	1 1
	REG FILE	1 1	RES DEPY GI	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

yellow

SEP 0 8 1987

Docket No. 50-400
License No. NPF-63

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-400/87-32

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by P. T. Burnett on August 10-14, 1987. The inspection included a review of activities authorized for your Harris facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

We understand it to be your intent to perform the loss of 100% electric load test no later than November 30, 1987, and that the test will be performed as described in FSAR 14.2.12.2.18 and Regulatory Guide 1.68, paragraph n.n with only the following exceptions: (1) Acceptance criterion 1 will be deleted, since reactor and turbine trips are now expected and (2) The plant's electrical distribution system may deviate from normal alignment to the extent necessary to assure that the turbine generator is subjected to the maximum credible overspeed.

If this is not your firm intention, please inform this office upon receipt of this letter.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

8709140201 870908
PDR ADOCK 05000400
G PDR

11
IEO 1

SEP 0 8 1987

Carolina Power and Light Company

2

The responses directed by this letter and its enclosure are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ORIGINAL SIGNED BY
ALAN R. HERDT

Alan R. Herdt, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
R. A. Watson, Vice President
Harris Nuclear Project
D. L. Tibbitts, Director of Regulatory
Compliance
J. L. Willis, Plant General Manager

bcc w/encl:
C. Barth, OGC
NRC Resident Inspector
A. Upchurch, Chairman, Triangle J^a
Council of Governments
Document Control Desk
State of North Carolina

RII

PTBurrnext:cc

08/27/87

RII

FJape

08/27/87

RII

for P. Fredrickson

08/27/87

