APR 2 3 1990

Docket No. 50-315 Docket No. 50-316

Indiana Michigan Power Company ATTN: Mr. Milton P. Alexich Vice President Nuclear Operations Division 1 Riverside Plaza Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Messrs J. Foster, D. Barss, and others of this office on April 2-6, 1990, of activities at the D.C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Facility Operating Licenses No. DPR-58 and No. DPR-74, and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosures, will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger, Chief

Reactor Programs Branch



Enclosure: Inspection Reports No. 50-315/90003(DRSS); No. 50-316/90004(DRSS)

yes

See Attached Distribution

RÍII RÍII دیدی Foster/lms / Barss

yes

yes
ŔIII
ယ် Snell
A/20/20





Indiana Michigan Power Company

2

Distribution

cc w/enclosure: A. A. Blind, Plant Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII James R. Padgett, Michigan Public Service Commission EIS Coordinator, USEPA Region 5 Office . Michigan Department of Public Health D. Bement, FEMA, Region V P. Emiskeen EDP NDP



