

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8901180381 DOC. DATE: 89/01/13 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 AUTH. NAME: WATSON, R.A. AUTHOR AFFILIATION: Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Eddy Current Exam CP&L Co Shearon Harris Nuclear Power Plant Unit 1 SGs A, B & C Aug & Sept 1988."

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 263
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES: Application for permit renewal filed. 05000400

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
	PD2-1 LA		1	0	PD2-1. PD		5	01
	BUCKLEY, B		1	1				
INTERNAL:	ACRS		02	02	AEOD/DSP/TPAB		1	1
	ARM/DAF/LFMB		1	0	NRR/DEST/MEB 9H		1	1
	NRR/DEST/MTB 9H		1	1	NUDGS-ABSTRACT		1	1
	OGC/HDS1		1	0	REG FILE 01		1	1
	RES/DSIR/EIB		1	1				
EXTERNAL:	EG&G ROCKHOLD, H		1	3	LPDR		1	1
	NL 007 HEMMING		1	3	NRC PDR		1	1
	NSIC		1	1				

Limited Dist.

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 26 ENCL 12

R
I
D
S
/
A
D
D
S

MA 2
9/1

100

100

100

100

100

100

CP&L

Carolina Power & Light Company

HARRIS NUCLEAR PROJECT
P.O. Box 165
New Hill, North Carolina 27562

JAN 13 1989

File Number: SHF/10-13510C
Letter Number: HO-880252 (O)

Document Control Desk
United States Nuclear Regulatory Commission
Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT
DOCKET NO. 50-400
LICENSE NO. NPF-63
SPECIAL REPORT
STEAM GENERATOR TUBE INSERVICE INSPECTION RESULTS

Gentlemen:

In accordance with Technical Specifications 4.4.5.5.b and 6.9.2 for the Shearon Harris Nuclear Power Plant, Unit No. 1, Carolina Power and Light Company hereby submits this Special Report. This Special Report provides the results of the steam generator tube inservice inspections performed during the Harris Plant's first refueling outage in August and September 1988.

Very truly yours,

R. A. Watson

R. A. Watson
Vice President
Harris Nuclear Project

MGW:dj

Enclosure

cc: Mr. R. A. Becker (NRR)
Mr. W. H. Bradford (NRC - SHNPP)
Mr. M. L. Ernst (NRC - RII)

8901180381 890113
PDR WADOCK 05000400
PDC

D

A047
11

MEM/HO-8802520/1/OS1

CONFIDENTIAL