ACCELERATED DISTRIBUTION DEMONSTRATION

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

S

D

R

S


	CESSION NBR:9007170092 DOC.DATE: 90/07/05 NOTARIZED: NO ACIL:50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina AUTH.NAME AUTHOR AFFILIATION	DOCKET # 05000400						
	COLLINS, D.M. Region 2, Ofc of the Director							
	RECIP. NAME RECIPIENT AFFILIATION							
	EURY,L.W. Carolina Power & Light Co.							
	SUBJECT: Forwards Insp Rept 50-400/90-12 on 900611-15. Violation noted but not cited.							
	DISTRIBUTION CODE: IE06D COPIES RECEIVED:LTR _ ENCL _ SIZE: TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation	on Respons						
-	NOTES: Application for permit renewal filed.	05000400						


	RECIPIENT ID CODE/NAME PD2-1 LA BECKER, D	COPII LTTR 1 1	ES ENCL 0 1	RECIPIENT ID CODE/NAME PD2-1 PD	COPI LTTR 1	£
INTERNAL:		2	2	AEOD/ANDERSON,R	1	1
	AEOD/DSP	1	1	COLLINS, D RGN 2	1	1
	NMSS/LLOB 5E4	1	1	NMSS/SGDB 4E4	1	1
	NRR/DLPQ/LPEB10	1	1	NRR/DOEA/OEAB11	1	1
	NRR/DREP/PRPB11	2	2	NRR/PMAS/ILRB12	1	1
	NUDOCS-ABSTRACT	1	1	OE DIR	1	1
	OGC/HDS1	1	1	REG FILE 02	ī	ī
	RES	1	1	RGN2 DRSS/RPB	1	1 .
	RGN2 FILE 01	1	1	RGN4 MURRAY, B	1	ī
EXTERNAL:	EG&G SIMPSON, F	2	2	LPDR	1	1
	אפר סחפ	1	1	NSTC	า	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

DTAL NUMBER OF COPIES REQUIRED: LTTR ENCL 28 27





Carolina Power and Light Company ATTN: Mr. Lynn W. Eury Executive Vice President Power Supply P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-400/90-12

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by D. A. Seymour on June 11-15, 1990. The inspection included a review of activities authorized for your Shearon Harris facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The enclosed Inspection Report identifies activities that appeared to violate NRC requirements that are not cited; therefore, a response is not required.

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ORIGINAL SIGNED BY JOHN P. POFTER

Douglas M. Collins, Chief Emergency Preparedness and Radiological Protection Branch Division of Radiation Safety and Safeguards

Enclosure: NRC Inspection Report

cc w/encl: (See page 2)

9007170092 900705 PUR ADOCK 05000400 PDC

TEOL

cc w/encl: R. B. Richey, Manager Harris Nuclear Project Box 165 New Hill, NC 27562

C. S. Hinnant
Plant General Manager
Harris Nuclear Project
Box 165
New Hill, NC 27562

D. L. Tibbitts, Director Regulatory Compliance Harris Nuclear Project P. O. Box 165 New Hill, NC 27562

Richard E. Jones
General Counsel
Carolina Power & Light Company
P. O. Box 1551
Raleigh, NC 27602

Dayne H. Brown, Director
Division of Radiation Protection
N. C. Department of Environment,
Health & Natural Resources
P. O. Box 27687
Raleigh, NC 27611-7687

bcc w/encl:
C. Barth, OGC
A. Upchurch, Chairman, Triangle J
 Council of Governments
Document Control Desk

NRC Resident Inspector
U.S. Nuclear Regulatory Commission
Route 1, Box 315B
New Hill, NC 27562

RII:DRSS RII:DRSS RII:DRP
DSeymour TDecker HDance
7/4/90 7/5/90