

CP&L  
NRC REGION II  
Carolina Power & Light Company GEORGIA

82 JUN 14 P 1: 48

TEHQ FILE COPY

CQAD 82-984

June 10, 1982

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

This letter is in reference to your letter of January 18, 1982, referring to Inspection Report 50-400/401/402/403/81-25 for Shearon Harris Nuclear Power Plant. Our letter CQAD 82-442 indicated that full compliance for violation B identified in Appendix A of the Inspection Report would be complete by May 1, 1982. This particular violation was also identified as a nonconforming condition by our site quality assurance organization and documented in Deficiency and Disposition Report number 746.

On December 22, 1981, the NRC (Mr. C. Julian) was notified by telephone, that the condition was considered potentially reportable per the provisions of 10CFR50.55(e). This notification was verified by our letter CQAD 82-105, dated January 20, 1982, to Mr. James P. O'Reilly which also indicated that the reportability evaluation would be completed by May 1, 1982.

Reinspection of the items in question was completed prior to May 1, 1982, but evaluation of the ability of the hangers to sustain design loads was not complete at that time. On May 3, 1982, our letter CQAD-82-791 to Mr. James P. O'Reilly informed the NRC that we anticipated completion of the reportability evaluation by June 15, 1982. We failed to recognize that a supplementary response to the violation, indicating a revised date for full compliance, should be submitted. Mr. W. Kleinsorge discovered this oversight during his on-site review of open 10CFR50.55(e) items May 1 through May 4, 1982.

8208160479 820610  
PDR ADDCK 05000400  
Q PDR

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

IED1

20. 4. 4.

2. 1. 19

D

1. 1. 19

2. 1. 19

3. 1. 19

4. 1. 19

5. 1. 19

6. 1. 19

7. 1. 19

8. 1. 19

9. 1. 19

10. 1. 19

11. 1. 19

12. 1. 19

13. 1. 19

14. 1. 19

15. 1. 19

16. 1. 19

17. 1. 19

18. 1. 19

19. 1. 19

20. 1. 19

21. 1. 19

22. 1. 19

23. 1. 19

24. 1. 19

25. 1. 19

26. 1. 19

27. 1. 19

28. 1. 19

29. 1. 19

30. 1. 19

31. 1. 19

32. 1. 19

33. 1. 19

34. 1. 19

35. 1. 19

36. 1. 19

37. 1. 19

38. 1. 19

39. 1. 19

40. 1. 19

41. 1. 19

42. 1. 19

43. 1. 19

44. 1. 19

45. 1. 19

46. 1. 19

47. 1. 19

48. 1. 19

49. 1. 19

50. 1. 19

51. 1. 19

52. 1. 19

53. 1. 19

54. 1. 19

55. 1. 19

56. 1. 19

57. 1. 19

58. 1. 19

59. 1. 19

60. 1. 19

61. 1. 19

62. 1. 19

63. 1. 19

64. 1. 19

65. 1. 19

66. 1. 19

67. 1. 19

68. 1. 19

69. 1. 19

70. 1. 19

71. 1. 19

72. 1. 19

73. 1. 19

74. 1. 19

75. 1. 19

76. 1. 19

77. 1. 19

78. 1. 19

79. 1. 19

80. 1. 19

81. 1. 19

82. 1. 19

83. 1. 19

84. 1. 19

85. 1. 19

86. 1. 19

87. 1. 19

88. 1. 19

89. 1. 19

90. 1. 19

91. 1. 19

92. 1. 19

93. 1. 19

94. 1. 19

95. 1. 19

96. 1. 19

97. 1. 19

98. 1. 19

99. 1. 19

100. 1. 19

Engineering evaluation of the items in question is still anticipated to be complete by June 15, 1982 and the Date When Full Compliance Will Be Achieved is revised to July 2, 1982.

Thank you for your consideration in this matter.

Yours very truly,



H. R. Banks - Manager  
Corporate Quality Assurance

NJC/gea (206)

cc: Mr. J. A. Jones

Handwritten marks and scribbles in the top right corner.

Faint, illegible text spanning the width of the page near the top.

Faint, illegible text located in the upper left quadrant.

Faint, illegible text located in the middle right area.

Faint, illegible text located near the bottom right edge.