

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9408120260 DOC. DATE: 94/08/09 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 AUTH. NAME AUTHOR AFFILIATION
 ROBINSON, W.R. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

See Reports

SUBJECT: Forwards "ISI Summary 1st Interval, 2nd Period, 5th Refueling
 Outage 1-2-05 Completed 940803," in accordance w/ASME Boiler
 & PV Code, Section XI, Article IWA-6220(b).

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 200
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES: Application for permit renewal filed. 05000400

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD2-1 LA		1	0		PD2-1 PD		1	
	LE, N		2	2					
INTERNAL:	ACRS		6	6		AEOD/DSP/ROAB		1	1
	NRR/DE/EMEB		1	1		NRR/EMCB		1	1
	NUDOCS-ABSTRACT		1	1		OC/LEDCB		1	0
	OGC/HDS2		1	0		<u>REG FILE</u>	01	1	1
	RES/DSIR/EIB		1	1					
EXTERNAL:	EG&G BROWN, B		1	1		EG&G RANSOME, C		1	1
	NRC PDR		1	1		NSIC		1	1

Limited Dist.

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR **14** ENCL **11**

P
R
I
O
R
I
T
Y

1

D
O
C
U
M
E
N
T

Limiteq Dist.

01 011
01 011

01 011

01 011



Carolina Power & Light Company
PO Box 165
New Hill NC 27562

William R. Robinson
Vice President
Harris Nuclear Plant

AUG 09 1994

File Number: HO-940351

SERIAL: HNP-94-065

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555


SHEARON HARRIS NUCLEAR POWER PLANT
DOCKET NO. 50-400/LICENSE NO. NPF-63
INSERVICE INSPECTION REPORT

Gentlemen:

In accordance with the reporting requirements of the ASME Boiler and Pressure Vessel Code, Section XI, Article IWA-6220(b), Carolina Power & Light Company (CP&L) hereby submits Shearon Harris Nuclear Power Plant (SHNPP) Inservice Inspection results. The enclosed report covers the inspections performed during the fifth refueling outage in the first inspection interval.

Questions regarding this matter may be referred to Mr. R. W. Prunty at (919) 362-2030.

Sincerely,




W. R. Robinson

SDC/sdc

c: Mr. S. D. Ebnetter (w/ enclosure)
Mr. N. B. Le (w/o enclosure)
Mr. J. E. Tedrow (w/ enclosure)
Mr. Billy Walker (w/ enclosure)
Honorable Hugh Wells (w/o enclosure)

120109



A047
11



Handwritten marks or scribbles in the top right corner.



INSERVICE INSPECTION SUMMARY

1st Interval, 2nd Period,
5th Refueling Outage
1-2-05

Completed August 3, 1994

Carolina Power & Light Company
P. O. Box 1551
Raleigh, NC 27602

Shearon Harris Nuclear Power Plant - Unit 1
P. O. Box 165
New Hill, NC 27562

Commercial Operation May 2, 1987

50-400

letter dtd 8/9/94

9408120260