

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
716 Edney Building

January 8, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

REGULATORY DOCKET FILE COPY

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/7823

The enclosed report provides details concerning reactor high pressure switches
PS-3-204A and B that exceeded the technical specification limits specified
in table 3.2.B during normal operation while performing surveillance testing.
This report is submitted in accordance with Browns Ferry unit 1 technical
specification 6.7.2.b.(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)
cc (Enclosure):
Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

A002
5
111
5
24

