

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
716 Edney Building

July 3, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/7916

The enclosed report provides details concerning pressure switches PS-1-81A
and B and PS-1-91A and B setpoints which exceeded Technical Specification
Table 3.1.A limits by three to eight psig during normal operation while
performing Surveillance Instruction 4.1.A-14, Turbine First Stage Pressure
Permissive - Functional Test and/or Calibration. This report is submitted
in accordance with Browns Ferry unit 2 Technical Specifications 6.7.2.b.1.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

REGULATORY DOCKET FILE COPY

A002
5/11

July 2, 1950

Mr. J. B. ...
Director, ...
Office of ...
Washington, D. C.

Dear Sir:

Reference is made to ...
...

...

Sincerely yours,

...

...

...

(2) ...

(1) ...

(1) ...

...

(1) ...

...

...

Handwritten notes or signature