



NORMAN W. CURTIS  
Vice President-Engineering & Construction-Nuclear  
821-5381

July 23, 1980

Mr. Boyce H. Grier  
Director, Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
UPDATE IN THE STATUS OF IMPROPER SAFETY  
CLASSIFICATION FOR SOLENOID VALVES  
ERs 100450/100508      FILE 840-4/900-10  
PLA-515


Reference: PLA-483 dated May 13, 1980

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of the subject deficiency under the provisions of 10CFR50.55(e).

PP&L has been advised by our architect engineer, Bechtel Power Corporation, that a final report on MCAR 1-55, which documents this condition, will be available in October, 1980. Consequently, we expect to provide our final report to the Commission in November, 1980.

Very truly yours,



N. W. Curtis  
Vice President-Engineering & Construction-Nuclear

FLW:mcb

cc: Mr. Victor Stello (15)  
Director-Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. G. McDonald, Director  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Robert M. Gallo  
U. S. Nuclear Regulatory Commission  
P. O. Box 52  
Shickshinny, Pennsylvania 18655

PENNSYLVANIA POWER & LIGHT COMPANY

B019  
S  
1/0

