

PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

February 2, 1979

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
UPDATE OF INTERIM REPORT REGARDING
UNDERSIZED WELDS ON SAFETY RELATED PIPE HANGERS
DOCKET NOS: 50-387 and 50-388
LICENSE NOS: CPPR-101 & CPPR-102
ERs 100450/100508 FILE 840-4
PLA-316

Dear Mr. Grier:

My letter, PLA-239 of April 16, 1978, provided supplemental information regarding the subject deficiency and the inspection program and subsequent corrective actions which were taken to assess and assure the acceptability of SSES safety related pipe hangers for which ITT-Grinnell is the supplier.

In the referenced letter you were advised that PP&L anticipated submitting a final definitive report of the deficiency by February 1, 1979. However, in the final compilation, PP&L determined that the report submitted to us by Bechtel Power Corporation on January 29, 1979 requires further clarification and elaboration. Therefore, on February 1, 1979 Mr. A. R. Sabol, PP&L, advised Mr. R. McGaughy of NRC Region I accordingly and requested and received an extension of sixty (60) days for submittal of said final definitive report.

Very truly yours,,

N. W. Curtis

N. W. Curtis
Vice President-Engineering & Construction

ARS:mcb

REGULATORY DOCKET FILE COPY

*B019
5/10*

7902060180

PENNSYLVANIA POWER & LIGHT COMPANY

Mr. Boyce H. Grier

- 2 -

February 2, 1979

cc: Mr. J. G. Davis (15)
Acting Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo (1)
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655