

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7905110300 DOC. DATE: 79/05/11 NOTARIZED: NO DOCKET #
 FACIL: 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1, PENNSYLV 05000387
 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2, PENNSYLV 05000388
 AUTH. NAME: AUTHOR AFFILIATION
 CURTIS, N.W. PENNSYLVANIA POWER & LIGHT CO.
 RECIP. NAME: RECIPIENT AFFILIATION
 GRIER, B.H. REGION 1, PHILADELPHIA, OFFICE OF THE DIRECTOR

SUBJECT: DISCUSSES 781103 DEFICIENCY REPT RE SSE SYS STANDBY DIESEL GENERATOR. SAFETY IMPACT TO BE EVALUATED & RESULTS TRANSMITTED BY 790525.W/781103 REPT.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

SEND I + E 3 CYS FSAR + ALL AMDTS. LA 1cy EVERYTHING. (ORNL)

NOTES: -----

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	14 PM MINER	1	1	15 BCLWR 3	1	1
	20 LA LWR 3	1	1	21 ADVASSALLO	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	19 AD SYS/PROJ	1	1
	22 DIR DPM	1	1	23 OELD	1	1
	AD/SITE TECH	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	STRUCT ANLYS BR	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

JUN 8 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 43

MA 1

60



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

MEMORANDUM FOR: TERA Corp.
FROM: US NRC/TIDC/Distribution Services Branch
SUBJECT: Special Document Handling Requirements

1. Please use the following special distribution list for the attached document.

*Please Re-generate Ride
Form Using Distribution
13019 and Jacket Number
50-387/388*

Thanks

2. The attached document requires the following special considerations:

- Do not send oversize enclosure to the NRC PDR.
 Only one oversize enclosure was received - please return for Regulatory File storage.
 Proprietary information - send affidavit only to the NRC PDR
 Other: (specify)

cc: DSB Files

Jim McKnight
TIDC/DSB Authorized Signature



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

MAY 11, 1979

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
612 Park Avenue
King of Prussia, Pennsylvania 18406

SUSQUEHANNA STEAM ELECTRIC STATION (SSES)
COOPER-BESSEMER COMPANY REPORT OF A
DEFICIENT PART IN THE SSES STANDBY DIESEL-GENERATOR
ERS 100450/100508 FILE 840-4
PLA-352

Dear Mr. Grier:

This relates to a deficiency which Cooper-Bessemer had reported to the Commission on November 3, 1978 under the provisions of 10CFR Part 21. The report stated that Cooper Energy Services, supplier of the emergency standby diesel-generators for SSES, had, during performance testing of engines similar to those for SSES, found that the surface of a roller pin in a crosshead assembly had exhibited abnormal wear. It was further stated that, though no engine shutdown nor malfunction had been experienced, it was felt that, for longer periods of engine operation, the abnormal wear condition could progress far enough to cause the engine to malfunction.

Although C.E.S. had reported the condition on November 3, 1978, it was not until April 25, 1979, when NRC Resident Inspector R. M. Gallo provided A. R. Sabol, PP&L, a copy of the C.E.S. report, that PP&L Susquehanna Project personnel became aware of the report.

Therefore, since the reporting responsibility under 10CFR Part 21 has already been discharged by C.E.S., PP&L recognizes its remaining responsibility for evaluating the condition under the terms of 10CFR 50.55(e).

Based upon the C.E.S. report, we conclude that the deficiency has potential for reportability and consider the details of the C.E.S. report to serve as an interim report in satisfaction of the provisions of 10CFR 50.55(e). However, we intend to further evaluate the safety impact of the deficiency

7905110300

B019
S
111

Mr. Boyce H. Grier

- 2 -

and will advise the Commission of our final determination within thirty (30) days.

Very truly yours,



N. W. Curtis
Vice President-Engineering & Construction

Attachments

ARS:mcb

cc: Mr. J. G. Davis (15)
Acting Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655