### REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8812010310 DOC.DATE: 88/11/29 NOTARIZED: NO DOCKET # FACIL:50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee 05000260 AUTH.NAME AUTHOR AFFILIATION

GRIDLEY, R. Tennessee Valley Authority

RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Forwards revised cover ltr for Safety Sys Functional Insp

Rept BFA 88811.W/o encl.

DISTRIBUTION CODE: D030D COPIES RECEIVED:LTR  $\underline{l}$  ENCL  $\underline{\mathcal{O}}$  SIZE: $\underline{\underline{\mathcal{O}}}$  TITLE: TVA Facilities - Routine Correspondence

NOTES:1 Copy each to: S.Black, J.G.Partlow, S.Richardson B.D.Liaw, F.McCoy.

05000260

D

•	RECIPIENT ID CODE/NAME SIMMS,M	COPIES LTTR ENCI 1 1	RECIPIENT ID CODE/NAME PD	COPIES LTTR ENCL 1 1
	GEARS, G	1 1		
INTERNAL:		1 1	ADM/LFMB	1 0
	NUDOCS-ABSTRACT REG FILE 01	1 1	OGC/HDS2	1 0
EXTERNAL:	LPDR	1	NRC PDR	1 1
	NSIC	1 þ,		1

m/A-H

Rec'd W/out Encl

NOTE TO ALL "RIDS" RECIPIENTS:

NOTES:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL

S)

SADD

## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

5N 157B Lookout Place

# NOV 29 1988

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Gentlemen:

In the Matter of Tennessee Valley Authority

Docket No. 50-260

BROWNS FERRY NUCLEAR PLANT (BFN) - UNIT 2 - SAFETY SYSTEM FUNCTIONAL INSPECTION (SSFI) REPORT NO. BFA 88811

TVA is submitting a revised cover letter for the subject report as requested by G. E. Gears, TVA Project Manager, NRC Office of Special Projects.

SSFI Report No. BFA 88811 considers the emergency equipment cooling water and the residual heat removal service water to be functional. The inspection was a TVA managed task with joint participation by TVA and Energy Resources Company, International (ERCI).

Currently, affected BFN organizations are preparing recommendations for each inspection observation. These recommendations and subsequent corrective actions should provide confidence in the functional readiness and restart of BFN.

The enclosures do not contain proprietary information as previously reported. The contractor's representative, Gary J. Overbeck of ERCI, states that their inspection methods are no longer proprietary information. Therefore, please withdraw the proprietary statement of our earlier submittal.

If you have any questions, please telephone Patrick Carier at (205) 729-3570.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. Gridley, Manager Nuclear Licensing and Regulatory Affairs

Enclosures cc: See page 2

o Recot End

8812010310 881129 PDR ADOCK 05000260 P PDC

An Equal Opportunity Employer

. • • . •

# U.S. Nuclear Regulatory Commission

### cc (Enclosures):

Ms. S. C. Black, Assistant Director for Projects TVA Projects Division U.S. Nuclear Regulatory Commission One White Flint, North 11555 Rockville Pike Rockville, Maryland 20852

Mr. F. R. McCoy, Assistant Director for Inspection Programs TVA Projects Division U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Browns Ferry Resident Inspector Browns Ferry Nuclear Plant Route 12, Box 637 Athens, Alabama 35611 The state of