

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7901050124 DOC. DATE: 78/12/28 NOTARIZED: NO
 FACIL: 50-220 NINE MILE POINT #1, NIAGARA MOHAWK POWER CORP.
 AUTH. NAME: HEDRICK, M.C. AUTHOR AFFILIATION: NIAGARA MOHAWK PWR
 RECIP. NAME: RECIPIENT AFFILIATION

DOCKET #
05000220

SUBJECT: LER 78-041/04T-0 on 781220: during impingement sampling only 23 samples (22 hourly samples & one 2-hour sample) were collected instead of 24 samples required, caused by one-time personnel scheduling change.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: INCIDENT REPORTS

NOTES:


ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC <i>ORB#3</i>	4	4			
INTERNAL:	01 <u>REG FILE</u>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 HANAUER	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

JAN 8 1979

T

A012-4

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43



December 28, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220
LER 78-41/04T-0
Nine Mile Point Nuclear Station #1

Dear Mr. Grier:

Section 3.1.2.a of the Environmental Technical Specifications requires that on Wednesday of each week hourly impingement samples will be collected. Contrary to this requirement, on December 20, 1978, only 23 samples were collected. The 23 samples consisted of 22 one hour samples and 1 two hour sample.

The contractor technician who had been on site collecting the impingement samples left prior to his relief's arrival. When the relief technician did arrive, she was detained by the security force while an investigation for compliance with ANSI 18.17 Section 4.3(2) was conducted. A combination of these two circumstances resulted in one hourly traveling screen wash not being sampled. All fish during this period were collected, but in one 2-hour sample instead of 2 hourly samples.

Contractor supervision instructed the technicians not to leave the site until relieved.

This incident is considered to have minimal impact.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President -
Electric Production

mtm