

LICENSEE EVENT REPORT

CONTROL BLOCK: _____

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| N | Y | N | M | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 57 CAT 58

CON'T

| REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 7 | 0 | 5 | 1 | 7 | 7 | 9 | 8 | 0 | 6 | 1 | 4 | 7 | 9 | 9

7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| During refueling outage, after an evaluation of TLD and film badge, it
 | was discovered that a radiographer received a technical overexposure of
 | 3790 millirem for the second quarter of 1979. No safety implications
 | resulted from this event.
 |
 |
 |

| SYSTEM CODE | Z | Z | 11 | CAUSE CODE | A | 12 | CAUSE SUBCODE | F | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16

7 8 9 11 12 13 18 19 20

| LER/RO REPORT NUMBER | EVENT YEAR | 7 | 9 | SEQUENTIAL REPORT NO. | 0 | 1 | 1 | OCCURRENCE CODE | 0 | 3 | REPORT TYPE | L | REVISION NO. | 0

17 21 22 23 24 26 27 28 29 30 31 32

| ACTION TAKEN | X | FUTURE ACTION | Z | EFFECT ON PLANT | Z | SHUTDOWN METHOD | Z | HOURS | 0 | 0 | 0 | 0 | ATTACHMENT SUBMITTED | N | NPRD-4 FORM SUB. | N | PRIME COMP. SUPPLIER | Z | COMPONENT MANUFACTURER | Z | 9 | 9 | 9

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| The cause of the overexposure is unknown at this time and is still being
 | investigated. This resulted in minimal safety implications.
 |
 |
 |

| FACILITY STATUS | H | % POWER | 0 | 0 | 0 | OTHER STATUS | 30 | NA | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | 32 | On the basis of High TLD reading on 5/15

7 8 9 10 12 13 44 45 46 80

| ACTIVITY CONTENT RELEASED | Z | OF RELEASE | Z | AMOUNT OF ACTIVITY | 35 | NA | LOCATION OF RELEASE | 36 | NA

7 8 9 10 11 44 45 80

| PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | TYPE | Z | DESCRIPTION | 39 | NA

7 8 9 11 12 13 80

| PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | DESCRIPTION | 41 | NA

7 8 9 11 12 80

| LOSS OF OR DAMAGE TO FACILITY TYPE | Z | DESCRIPTION | 43 | NA

7 8 9 10 80

| PUBLICITY ISSUED | N | DESCRIPTION | 45 | NA

7 8 9 10 80

7906220417

7906220417

