

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

COPY

April 21, 1980

Mr James G Keppler Office of Inspection and Enforcement Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 80-006 - PURGE VALVE T-RING AIR SUPPLIES

On the reverse side is Licensee Event Report 80-006 which is reportable under Technical Specification 6.9.2.B.4.

David P Hoffman (Signed)

David P Hoffman Nuclear Licensing Administrator

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector-Palisades

> A007 5

## PALISADES PLANT

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	MIPALI 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 6 5 CAT 58
CON'T	REPORT L 6 0 5 10 0 0 2 5 5 7 1 1 1 1 0 7 9 8 0 4 2 1 8 0 9  EVENT DESCRIPTION AND REPORT BY CONSEQUENCES (1)
0 2	During routine surveillance of containment purge valves, it was found that
0 3	the redundant T-ring air supplies for the 12-inch and 48-inch purge valves
0 4	had leakage in excess of acceptance criteria. Normal air supply was
0 5	Loperable. Condition classified reportable under TS 6.9.2.B.4 on 3-21-80.
06	
0 7	
0 8 7 8	
0 9 7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  17) REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32
4.	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER F 18 B 19 Z 20 Z 21 O O O O O N 23 Y 24 A3 25 F 1 2 5 26
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [ Leaks were primarily through fittings and valve packings. Replacement ]
	of CV-1806 and CV-1807 with blank flanges has been completed. Repairs
12	to T-ring air supplies to CV-1812 and 1814 will be completed prior to
1 3	start-up.
14	
1 5 7 8	ACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  LG 38 D 10 12 13 13 EVALUATION OF Test Results 50 10 10 12 13 13 15 15 15 15 15 15 15 15 15 15 15 15 15
1 6	CTIVITY CONTENT ILEASED OF RELEASE AMOUNT OF ACTIVITY (35)  LOCATION OF RELEASE (36)  NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY (35)  NA  15  NA  80
1 7	NUMBER TYPE DESCRIPTION (39)  O O O 37 Z 38 NA  9 PERSONNEL IN HIBLES  BO  BO
1 8	NUMBER DESCRIPTION (41)  O O O O O O O O O O O O O O O O O O O
1 9	SO LOSS OF DR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA J
2 0	PUBLICITY SSUED DESCRIPTION 45  NA NRC USE ONLY  NA
	9 10 68 69 80