

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

October 31, 1980

Mr James G Keppler Office of Inspection and Enforcement Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 -PALISADES PLANT - RESPONSE TO IE INSPECTION REPORT 80-17 -FIRE PREVENTION PROCEDURES

IE Inspection Report 80-17, dated October 8, 1980, Implementation of Fire Prevention Procedures, identified an apparent item of noncompliance of the Palisades Plant Technical Specification Part 6.8.1(d). Our response to this infraction is as follows:

Item

Technical Specification Part 6.8.1(d) states, in part: "written procedures shall be...implemented...covering the...emergency plan implementation."

Contrary to the above, on August 28, 1980, the inspectors verified by direct observation during a tour of safety-related areas that fire plan implementing procedures parts 8.2 and 8.3 concerning the control of combustible material were not being implemented when accumulations of combustible material and improperly stored combustible material were observed in safety-related areas.

Response

S101090/7/

Corrective Action Taken and Results Achieved

On October 23 and 24, 1980, all department heads were advised of the various deficiencies in their respective areas. An inspection by the Plant Property Protection Section of these areas, noted in Paragraph 2 of the Subject Inspection Report, was conducted. With the exception of the wooden scaffolding (Item 2F(1)), the plastic containers of snubber oil (Item 2G(1)) and the wooden shipping crates (Item 2G(3)), the inspected areas had been cleaned up.

NUA 2 1990



Mr James G Keppler Palisades Plant October 31, 1980

Those items noted in 2G(2) and 2G(3) are contaminated and will be decontaminated and removed from the spent fuel pool area.

Corrective Action Taken To Avoid Further Noncompliance

Weekly inspections will be conducted by the Plant Property Protection Section. Items not in compliance with established Fire Protection Procedures will be noted. A report will be written with copies to be distributed to all department heads as well as the Plant Manager. If an item is noted on two consecutive inspections, it will be documented as such on the written report. Actions needed to correct this situation, should it arise, will be decided upon by the Plant Management.

Date When Full Compliance Will Be Achieved

Full compliance will be achieved by December 1, 1980.

David P Hoffman (Signed)

David P Hoffman Nuclear Licensing Administrator

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement Resident Inspector-Palisades 2