



AEROTEST OPERATIONS, INC.

3455 FOSTORIA WAY • SAN RAMON, CA 94583 • (925) 866-1212 • FAX (925) 866-1716

February 14, 2018

ATTENTION: Document Control Desk
U.S. Nuclear Regulatory Commission
White Flint North
11555 Rockville Pike
Rockville, MD 20852-2738

AEROTEST RADIOGRAPHY AND RESEARCH REACTOR
DOCKET NO. 50-228/LICENSE NO. R-98.

Updated Emergency Plan

Ladies and Gentlemen:

Enclosed please find the updated Emergency Plan for ARRR. (R-98). The changes comply with 10 CFR 50.54 q(3). This updated plan does not reduce the predecessor's effectiveness (dated February 2005); the changes are mainly administrative in nature. Therefore, the enclosed document is placed into service. (This document does not contain safeguards information.)

Should you have any questions or require additional information regarding this submission, please contact AO President David M. Slaughter, Ph.D. at (801) 631 5919 or dmsraven@gmail.com

Sincerely yours,

David M. Slaughter, Ph.D.
President and Reactor Administrator
Aerotest Operations, Inc.

Enclosures:

1. ARRR Emergency Plan

AD20
AX45
NRR