

G B Slade General Manager

Palisades Nuclear Plant: 27780 Blue Star Memorial Highway, Covert, MI 49043

February 18, 1994

Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

DOCKET 50-255 - LICENSE DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 92-031-01 - INADVERTENT ENGINEERED SAFETY FEATURE ACTUATION CAUSED BY INADEQUATE TEST PROCEDURES - SUPPLEMENTAL INFORMATION

Licensee Event Report (LER) 92-031-01 is attached. This supplemental report revises the corrective actions. The original corrective action to revise test connection drawings is no longer required because plant procedures were revised in such detail as to eliminate the need to revise these drawings to prevent recurrance of this event. Changes are denoted by a vertical line in the right margin. This event was originally reported in accordance with 10CFR50.73(a)(2)(iv) as an event that resulted in the actuation of an Engineered Safety Feature.

Gerald B Slade General Manager

CC Administrator, Region III, USNRC NRC Resident Inspector - Palisades

Attachment

9403100198 940218 PDR ADDCK 05000255 S PDR

