

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

BUFFALO NY FM GROUP
P.O. Box 1685
Williamsville, New York 14231-1685
Phone: 716-636-8902
Facsimile: 716-636-5794

Director of FSME

Attn: GLTS

USNRC

Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 1/31/2018 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015.

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact:

Sharon L Umiker 716-636-8902

Sincerely,



Todd E Lincoln, Facilities Manager

Encl.

29 Signs

1 of 2

SERIAL NUMBER SPREADSHEET

Company Name	Buffalo NY FM Group	Date	12-13-17
Address 1	1424 Maple R	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACQ-235/55
City/State	Williamsville, NY	Contact Name	Sharon L Umiker
Zip/Post Code	14224-1472	Contact Phone	716-636-8902
Country	United States	Contact FAX	716-636-5794
		Contact E-mail	umikersl@idschurch.org

(Buffalo Ward)

Room/Space
 ✓ 50
 ✓ 25+26
 double sided
 47 ✓
 ✓ 26
 ✓ 25
 ✓ 26
 ✓ 48
 1
 2
 1
 2
 ✓ 54
 ✓ 84
 ✓ 25

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	Safety-Lite	SLX60	014835	9	94	9.5 Ci
2	Safety-Lite	SLX60	014826-A	9	94	
3			014831-A	9	94	
4	Safety-Lite	SLX60	014803	9	94	
5		SLX60	014827	9	94	
6		SLX60	014830	9	94	
7		SLX60	014826	9	94	
8		SLX60	014802	9	94	
9		SLX60	014756	9	94	
10		SLX60	014838	9	94	
11		SLX60	014839	9	94	
12		SLX60	014754	9	94	
13		SLX60	014836	9	94	
14		SLX60	014837	9	94	
15		SLX60	014834	9	94	✓

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

15 (2 "double-side")
 1 of 2

2 of 2

SERIAL NUMBER SPREADSHEET

Company Name	Buffalo NY FM Group	Date	12-13-17
Address 1	1424 Maple Rd	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	F-MACQ-235155
City/State	Williamsville, NY	Contact Name	Sharon L Umiker
Zip/Post Code	14221	Contact Phone	716-636-8902
Country	United States	Contact FAX	716-636-5794
		Contact E-mail	umiker@slsldschurch.org

space#	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
25	SafetyLite	SLX60	014826-B	9	94	9.5
26	↓	SLX60	014831-B	9	94	9.5
47	↓		014833	9	94	9.5
47	↓		014840	9	94	9.5
46	↓		014755	9	94	9.5
46	↓		014841	9	94	9.5
46	↓		014751	9	94	9.5
46	↓		014757	9	94	9.5
54	↓		014753	9	94	9.5
30	↓		014832	9	94	9.5
11	↓	2000	A2516225	02	02	9.5
12	↓	2000	A2516275	02	02	9.5
15	↓	2040	A27654	7	02	9.5
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

13